AD-A035 574

COAST GUARD RESEARCH AND DEVELOPMENT CENTER GROTON CONN F/G 13/10 INVESTIGATION OF RECREAT ONA. BOAT STEERING AND CONTROL SYSTEMS.—ETC(U) APR 76 JA TAYLOR COR/DC-8/76

UNCLASSIFIED

LOCATION OF RECREAT ONA. BOAT STEERING AND CONTROL SYSTEMS.—ETC(U) APR 76 JA TAYLOR OF THE CONTROL SYSTEMS.

ETC. SYSTEMS AND THE CONTROL SYSTEMS APP 76 JA TAYLOR OF THE CONTROL SYSTEMS A



INVESTIGATION OF RECREATIONAL BOAT STEERING AND CONTROL SYSTEMS

John R. Taylor
USCG Research and Development Center
Avery Point
Groton, CT 06340



April 1976

Final Report

Document is available to the public through the National Technical Information Service, Springfield, Virginia 22161

Present for

DEPARTMENT OF TRANSPORTATION UNITED STATES COAST QUAND

Office of Research and Development Westington, D.C. 20090 DDC PROPULLING FEB 24 1897 ISINGEN ISINGEN

CAPY AVAILABLE TO DOC DOES NOT PENNT FULLY LEGISLE PRODUCTION

NOTICE

ACCEPACE

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no liability for its contents or use thereof.

The United States Government does not endorse products or manufacturers. Trade or manufacturers' names appear herein solely because they are considered essential to the object of this report.

The contents of this report reflect the views of the Coast Guard Research and Development Center, which is responsible for the facts and accuracy of data presented. This report does not constitute a standard, specification or regulation.

This report represents an in-depth study of the hazards and problems associated with outboard recreational boat steering and control systems. This report represents an in-depth study of the hazards and problems associated with outboard recreational boat steering and control systems. Emphasis is placed on the steering systems. Problem identification work is documented with a review of Coast Guard accident statistics and defect notification files. In addition, manufacturer warranty and liability files are summarized along with a field survey of suspect steering systems, accident investigations, and interviews with marine mechanics. Operational tests have been performed with instrumented test boats to document the level of loadings placed on a steering system obt during normal operation and extreme maneuvering situations. Results of laboratory tests on steering systems and their accessoriare discussed. Finally, the effectiveness and reliability of steering systems are assessed and compared to the industry-developed standard for outboard steering systems. 10. Key Words 11. Contribution Stetument 12. Sponsoring Apency Code 13. Type of Report and Period Covered 14. Sponsoring Apency Code 15. Sponsoring Apency Code 16. Abitract 17. Sponsoring Apency Code 18. Sponsoring Apency Code 19. Sponsori	1 Separ Nu	2. Government Accession No.	Technical Report Documentat 3. Recipient's Catalog No.
INVESTIGATION OF RECREATIONAL BOAT STEERING APT 76 INVESTIGATION OF RECREATIONAL BOAT STEERING INVESTIGATION OF RESEARCH AND STEERING INVESTIGATION OF RESEARCH AND SETTING THE PROPERTY OF THE PROPER			
AND CONTROL SYSTEMS. John R. Taylor 2. Perthodismy Organization None and Address U. S. Coast Guard Research and Development Center Arery Point Groton, Connecticut 06340 12. Sponsoring Agency Name and Address Department of Transportation U. S. Coast Guard Office of Research and Development Washington, DC 20590 15. Supplementary Notes This report represents an in-depth study of the hazards and problems associated with outboard recreational boat steering and control systems. Rmphasis is placed on the steering systems. Problem identification work is documented with a review of Coast Guard accident statistics and defect notification files. In addition, manufacturer warranty and liability files are summarized along with a field survey of suspect steering systems, accident investigations, and interviews with marine mechanics. Operational tests have been performed with instrumented test boats to document the level of loadings placed on a steering system both during normal operation and extreme maneuvering situations. Results of laboratory tests on steering systems and their accessori are discussed. Finally, the effectiveness and reliability of steering systems are assessed and compared to the industry-developed standard for outboard steering systems 18. Distribution Stortemen Document is available to the public through the National Technical Information Service, Springfield, VA 22161		Annual Colonia and the colonia	(1)
John R. Taylor John R. Taylor	INVESTIGATION OF RECREATION	ONAL BOAT STEERING	
John R. Taylor Ju. S. Coast Guard Research and Development Center Avery Point Groton, Connecticut 06340 12. Sponsoring Agency, Name and Address Department of Transportation U. S. Coast Guard Office of Research and Development Washington, DC 20590 15. Supplementery Notes 16. Abstract This report represents an in-depth study of the hazarda and problems associated with outboard recreational boat steering and control systems. Emphasis is placed on the steering systems. Problem identification work is documented with a review of Coast Guard accident statistics and defect notification files. In addition, manufacturer warranty and liability files are summarized along with a field survey of suspect steering systems, accident investigations, and interviews with marine mechanics. Operational tests have been performed with instrumented test boats to document the level of loadings placed on a steering system both during normal operation and extreme maneuvering situations. Results of laboratory tests on steering systems and their accessori are discussed. Finally, the effectiveness and reliability of steering systems are assessed and compared to the industry-developed standard for outboard steering systems 18. Distribution Stetument Document is available to the public through the National Technical Information Service, Springfield, VA 22161	AND CONTROL SISTEMS.		(12)14100
U. S. Coast Guard Research and Development Center Avery Point Groton, Connecticut 06340 12. Sponsoring Agency Name and Address Department of Transportation U. S. Coast Guard Office of Research and Development Washington, DC 20590 13. Supplementary Notes This report represents an in-depth study of the hazards and problems associated with outboard recreational boat steering and control systems. Emphasis is placed on the steering systems. Problem identification work is documented with a review of Coast Guard accident statistics and defect notification files. In addition, manufacturer warranty and liability files are summarized along with a field survey of suspect steering systems, accident investigations, and interviews with marine mechanics. Operational tests have been performed with instrumented test boats to document the level of loadings placed on a steering system both during normal operation and extreme maneuvering situations. Results of laboratory tests on steering systems and their accessori are discussed. Finally, the effectiveness and reliability of steering systems are assessed and compared to the industry-developed standard for outboard 17. Key Words 18. Distribution Stetement Document is available to the public through the National Technical Information Service, Springfield, VA 22161	7 Aviliar's)		8. Performing Organization Report No.
U. S. Coast Guard Research and Development Center Avery Point Groton, Connecticut 06340 11. Contract or Gront No. 765300E.02 12. Sponsoring Agency Nome and Address Department of Transportation U. S. Coast Guard Office of Research and Development Washington, DC 20590 15. Supplementary Notes 16. Abstract This report represents an in-depth study of the hazards and problems associated with outboard recreational boat steering and control systems. Emphasis is placed on the steering systems. Problem identification work is documented with a review of Coast Guard accident statistics and defect notification files. In addition, manufacturer warranty and liability files are summarized along with a field survey of suspect steering systems, accident investigations, and interviews with marine mechanics. Operational tests have been performed with instrumented test boats to document the level of loadings placed on a steering system both during normal operation and extreme maneuvering situations. Results of laboratory tests on steering systems and their accessori are discussed. Finally, the effectiveness and reliability of steering systems are assessed and compared to the industry-developed standard for outboard steering systems. 18. Diswibution Stevement Document is available to the public through the National Technical Information Service, Springfield, VA 22161			CGR DC-8/76
Avery Point Groton, Connecticut 06340 12. Sponsoring Agency Nome and Address Department of Transportation U. S. Coast Guard Office of Research and Development Washington, DC 20590 15. Supplementery Notes 16. Abstract This report represents an in-depth study of the hazards and problems associated with outboard recreational boat steering and control systems. Emphasis is placed on the steering systems. Problem identification work is documented with a review of Coast Guard accident statistics and defect notification files. In addition, manufacturer warranty and liability files are summarized along with a field survey of suspect steering systems, accident investigations, and interviews with marine mechanics. Operational tests have been performed with instrumented test boats to document the level of loadings placed on a steering system both during normal operation and extreme manuvering situations. Results of laboratory tests on steering systems and their accessori are discussed. Finally, the effectiveness and reliability of steering systems are assessed and compared to the industry-developed standard for outboard steering systems. 18. Distribution Statement Document is available to the public through the National Technical Information Service, Springfield, VA 22161	그들이 얼굴을 하는데 보다 아름이 보니고 있었다. 그런 경우를 모르는 것이 없다고 있다.		
12. Sponsoring Agency Name and Address Department of Transportation U. S. Coast Guard Office of Research and Development Washington, DC 20590 15. Supplementary Notes 16. Abstract This report represents an in-depth study of the hazards and problems associated with outboard recreational boat steering and control systems. Emphasis is placed on the steering systems. Problem identification work is documented with a review of Coast Guard accident statistics and defect notification files. In addition, manufacturer warranty and liability files are summarized along with a field survey of suspect steering systems, accident investigations, and interviews with marine mechanics. Operational tests have been performed with instrumented test boats to document the level of loadings placed on a steering system both during normal operation and extreme manuvering situations. Results of laboratory tests on steering systems and their accessori are discussed. Finally, the effectiveness and reliability of steering systems are assessed and compared to the industry-developed standard for outboard steering systems. 18. Distribution Statement Document is savailable to the public through the National Technical Information Service, Springfield, VA 22161	Avery Point		
12. Sponsoring Agency Name and Address Department of Transportation U. S. Coast Guard Office of Research and Development Washington, DC 20590 15. Supplementary Notes This report represents an in-depth study of the hazards and problems associated with outboard recreational boat steering and control systems. Emphasis is placed on the steering systems. Problem identification work is documented with a review of Coast Guard accident statistics and defect notification files. In addition, manufacturer warranty and liability files are summarized along with a field survey of suspect steering systems, accident investigations, and interviews with marine mechanics. Operational tests have been performed with instrumented test boats to document the level of loadings placed on a steering system both during normal operation and extreme maneuvering situations. Results of laboratory tests on steering systems and their accessori are discussed. Finally, the effectiveness and reliability of steering systems are assessed and compared to the industry-developed standard for outboard steering systems 15. Distribution Stetement Document is available to the public through the National Technical Information Service, Springfield, VA 22161	Groton, Connecticut 06340	0	
U. S. Coast Guard Office of Research and Development Washington, DC 20590 15. Supplementary Notes 16. Abstract This report represents an in-depth study of the hazarda and problems associated with outboard recreational boat steering and control systems. Emphasis is placed on the steering systems. Problem identification work is documented with a review of Coast Guard accident statistics and defect notification files. In addition, manufacturer warranty and liability files are summarized along with a field survey of suspect steering systems, accident investigations, and interviews with marine mechanics. Operational tests have been performed with instrumented test boats to document the level of loadings placed on a steering system both during normal operation and extreme maneuvering situations. Results of laboratory tests on steering systems and their accessoriare discussed. Finally, the effectiveness and reliability of steering systems are assessed and compared to the industry-developed standard for outboard steering systems. 17. Key Words 18. Distribution Stevent Document is available to the public through the National Technical Information Service, Springfield, VA 22161			A Type of Report and Period Covere
Office of Research and Development Washington, DC 20590 15. Supplementary Notes 16. Abstract This report represents an in-depth study of the hazards and problems associated with outboard recreational boat steering and control systems. Emphasis is placed on the steering systems. Problem identification work is documented with a review of Coast Guard accident statistics and defect notification files. In addition, manufacturer warranty and liability files are summarized along with a field survey of suspect steering systems, accident investigations, and interviews with marine mechanics. Operational tests have been performed with instrumented test boats to document the level of loadings placed on a steering system both during normal operation and extreme maneuvering situations. Results of laboratory tests on steering systems and their accessori are discussed. Finally, the effectiveness and reliability of steering systems are assessed and compared to the industry-developed standard for outboard steering systems. 17. Key Words 18. Distribution Stetement Document is available to the public through the National Technical Information Service, Springfield, VA 22161		ion	Final Repeat
Washington, DC 20590 15. Supplementary Notes 16. Abstract This report represents an in-depth study of the hazards and problems associated with outboard recreational boat steering and control systems. Emphasis is placed on the steering systems. Problem identification work is documented with a review of Coast Guard accident statistics and defect notification files. In addition, manufacturer warranty and liability files are summarized along with a field survey of suspect steering systems, accident investigations, and interviews with marine mechanics. Operational tests have been performed with instrumented test boats to document the level of loadings placed on a steering system both during normal operation and extreme maneuvering situations. Results of laboratory tests on steering systems and their accessori are discussed. Finally, the effectiveness and reliability of steering systems are assessed and compared to the industry-developed standard for outboard steering systems. 17. Key Words 18. Distribution Steinment Document is available to the public through the National Technical Information Service, Springfield, VA 22161		velopment	14. Sponsoring Agency Code
This report represents an in-depth study of the hazards and problems associated with outboard recreational boat steering and control systems. Emphasis is placed on the steering systems. Problem identification work is documented with a review of Coast Guard accident statistics and defect notification files. In addition, manufacturer warranty and liability files are summarized along with a field survey of suspect steering systems, accident investigations, and interviews with marine mechanics. Operational tests have been performed with instrumented test boats to document the level of loadings placed on a steering system both during normal operation and extreme maneuvering situations. Results of laboratory tests on steering systems and their accessoriare discussed. Finally, the effectiveness and reliability of steering systems are assessed and compared to the industry-developed standard for outboard steering systems systems. 17. Key Words 18. Distribution Stetement Document is available to the public through the National Technical Information Service, Springfield, VA 22161	Washington, DC 20590		
recreational boat, steering system Document is available to the public through the National Technical Information Service, Springfield, VA 22161	associated with outboard r Emphasis is placed on the is documented with a review	recreational boat steering as steering systems. Problem : ew of Coast Guard accident st	nd control systems. Identification work satistics and defect
22161	associated with outboard of Emphasis is placed on the is documented with a revision notification files. In adare summarized along with investigations, and intervibeen performed with instruplaced on a steering systematical situations. Results of large discussed. Finally, the are assessed and compared	recreational boat steering are steering systems. Problem is seering systems. Problem is seering are seed of Coast Guard accident standard a field survey of suspect standard survey of suspect survey survey of suspect survey survey of suspect survey of	and control systems. Identification work Estistics and defect Ey and liability files Exering systems, accident Operational tests have at the level of loadings Ion and extreme maneuvering Eystems and their accessors Elity of steering systems
19. Security Classif. (of r. s report) 20. Security Classif. (of this page) 21. No. of Pages 22. Price	Emphasis is placed on the is documented with a revie notification files. In adare summarized along with investigations, and interviewen performed with instruplaced on a steering systesituations. Results of lare discussed. Finally, the are assessed and compared steering systems. 17. Key Words 17. Key Words	recreational boat steering ar steering systems. Problem is we of Coast Guard accident so didition, manufacturer warrant a field survey of suspect so views with marine mechanics. Immented test boats to document both during normal operation aboratory tests on steering at the effectiveness and reliable to the industry-developed so distribution of the industry-developed states.	and control systems. Identification work Identification

Reproduction of completed page authorized

Form DOT F 1700.7 (3-72)


ACKNOWLEDGMENTS


The investigation of recreational boat outboard steering systems is a complex problem in that it has such an extreme range of application within the boating industry. To properly document a steering system and its problems the boat, outboard engine, and accessory manufacturer, as well as the steering system manufacturer himself must be involved.

To a great extent, this report was made possible by the cooperation given the Coast Guard Research and Development Center by members of the boating industry. In particular the author would like to thank representatives of the following firms who, through their time and research efforts, provided laboratory testing services, test equipment, research data, and professional expertise.

American Chain and Cable Co. Attwood Boating Industry Association Boston Whaler Chrysler Marine Detroit Marine Glastron

Marmac
Mercury Marine
Morse Controls
Outboard Marine Corp.
Sheller-Globe
Teleflex, Inc.





	1	11ell	333	residental	luna	· inthe	two versions
it Manual	1 29	inches inches test inches	Square inches square yards square miles scree	so de se	Part of the control o	įŀ	000 - 000 -
Approximate Conversions from Metric Massures	Meltiply by	13223	2582 288	0.035 2.2 1.1 VOLUME	2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.	9/5 (then add 32)	20 31 400 4180
Appreximate Con	} ! !	millimeters certimeters meters meters kilometers	square continuers square meters square kilometers hectures (10,000 m	greens hilograms tonnes (1000 kg)	Hers Hers Hers Oblice mens	Coteius Targetina	% - Q
	i	•	3-32	.9.	ī Te Te	ent ent	. 0 ± 00
52 2	z 12 6	E 61 91 21	9t St 9t Et	77 77 78		s • •	c= 1
lata.	latalat	alakalakala	kalatalatala	talatalatal	1111		inches
	į	55 e 5	ริการิง	•9.	111%	1 .	. del. 286.
Mossers]	continuters continuess meters kilemeters	square centimeter square meters square meters square kilometers hacteres	grams kilograms tommes		cubic meters	temperature lables, see NBS Msc. Publ. 286,
eraions to Metric	i	15 5 5 5 2 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	28222	MASS (weight) 28 0.46 0.9 VOLUME	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	TEMPERATURE (exact) 5.9 (after	subtracting 32) Scors and more detailed i
Approximate Corversions to Motric	1	1111		oweres pounds short tons (2000 to)	members subsequent that concess cape parts parts partes cabic test	Cubic yands TEMPE Fabrushait	temperature subtracting 32) -1 in z 2.54 resectivi. For other exect convexsions and note detailed tal Unite of Respits and Measures, Price 32.25, SD Catalog No. C13.10.286.
	1	1031	3333	••	illw		"1 in ± 2.54 in Units of Respire
				CONTRACTOR STATE			

Control of the second

TABLE OF CONTENTS

				Page
1.0	INTE	RODU	CTION GIANA TRACH LINT MANY ASSETS BEING BERNE	1
2.0	ОВЈЕ	CTI	VES GET SITT IS SHELL METURES SESSET TOOL !	1
3.0	CONS	TRA	INTS/CONDITIONS	1
4.0	R&DC	RE	SEARCH AND AND ADDRESS OF A STATE OF THE SEARCH	2
			thod of Approach sults	2
5.0	INDU	STR	Y SYSTEM TESTS	5
	5.1 5.2 5.3	Otl	boratory Cyclic Tests her Industry Tests mparison to ABYC P-17 Standard	10
6.0	CONC	LUS	IONS	17
7.0	RECO	MME	NDATIONS	17
APPE	NDIX	A -	STEERING AND CONTROL SYSTEM DEFECT NOTIFICATIONS CAMPAIGN SUMMARY	A-1
APPE	NDIX	в -	REQUIREMENTS FOR THE DOCUMENTATION OF RECREATIONAL BOAT STEERING AND CONTROL SYSTEMS	B-1
APPE	NDIX	c -	EXCERPTS FROM "FINDINGS FROM A SURVEY OF MARINE MECHANICS REGARDING STEERING SYSTEM FAILURES"	C-1
APPE	NDIX	D -	OUTBOARD MOTOR REMOTE STEERING SYSTEMS, ABYC PROJECT P-17	D-1
APPE	NDIX	E -	RECREATIONAL BOAT STEERING SYSTEM TESTING, OUTBOARD MARINE CORPORATION	E-1

LIST OF ILLUSTRATIONS

Figure		Page
1	Steering Load Traces from Full Motor Angle Accelerated Turns	6
2	Steering Load Traces Showing Effect of Trim Tab Adjustment	7
3	Motor Angle Drift with No Trim Tab	8
4	Speed, RPM, Steering Load Traces While Striking Submerged Object	9
5	Steering System Efficiency Envelopes	11
6	Output Load vs. Input Torque Envelopes	13
7	System Backlash vs. Input Torque	14

ANALYS TO STEEL HAND CONTROL OF TAXABLE OF TAXABLE

THE ROTTLES DESIGNATION THE SET CONTROL THE SET OF THE SET

1.0 INTRODUCTION

The initial investigation into the hazards and problems associated with steering and control systems on recreational boats was initiated by the Office of Boating Safety's TSR of 24 May 1973. Due to the complex nature of the systems (i.e., involvement of steering system, boat, engine, and accessory manufacturers) a great deal of industry cooperation ensued. As a result of industry/R&DC staff meetings, R&D Center participation in the BIA Steering Task Force, and R&DC contracts, a considerable amount of industry instrumented boat tests and laboratory system tests were performed to complement the testing conducted at the R&D Center. Active industry involvement was obtained from Outboard Marine Corporation, Mercury Marine, Morse Controls, Teleflex, Incorporated, Marmac, American Chain and Cable, Detroit Marine, Glastron, Attwood, and Sheller-Globe Corporation. Analysis of test results has shown that recreational boat steering systems (single outboard mechanical push-pull) are effective, reliable, and efficient in handling the load levels imposed by operational testing if properly installed and maintained. Furthermore, the safety standard developed by the BIA Steering Task Force (proposed ABYC P-17) sets realistic strength requirements from a safety standpoint and more importantly addresses the areas of corrosion, installation, and standardization of parts.

2.0 OBJECTIVES

The objectives of this task may be summarized as follows:

- a. To determine the exact steering and control hazards and their causes.
- b. To determine the actual loading to which a steering system is subjected and the parameters affecting this loading.
- c. To determine the effectiveness of current production steering systems in meeting the loads determined in (b), and the parameters affecting cable fatigue.
- d. To determine the efficiency and reliability of various steering systems in meeting the requirements of (b) and (c).
- e. And finally, to analyze all data and determine the need for Federal standards in these areas.

3.0 CONSTRAINTS/CONDITIONS

tricounty compared at the

It was felt that in order to accomplish this task within the desired time frame, two important considerations were: (1) a limitation of scope, and (2) considerable cooperation between the Coast Guard and industry. As to the former, this initial work was limited to mechanical push-pull steering systems as they are used in conjunction with single engine outboard powered craft. Through the efforts of the R&DC and Commandant (G-BBT) personnel, an excellent rapport was developed with the industry which led to membership on the BIA Task Force on steering

-ligabl of sylenization ster epili office of the continuous to selver

systems. A considerable amount of industry test data and equipment was thereby acquired to complement R&DC tests. Since most of this data was acquired at no cost to the Government, there is the additional constraint that much of the information is proprietary in nature.

4.0 R&DC RESEARCH

This section presents the procedures and results of the R&DC's cause identification work and instrumented boat tests.

4.1 Method of Approach

The identification of the exact steering and control hazards and their causes was separated into various levels of effort. These were:

- a. A review of the boating accident report files and the defect notification files associated with steering and control systems.
- b. Discussion and review of industry warranty and liability claim files.
- c. Investigation of steering and control system associated accidents.
- d. A field survey of boat mechanics and marine facilities to collect failed steering systems for a failure mode and effect analysis.

The procedures and maneuvers carried out during the instrumented boat tests were twofold in purpose. First to document the normal operating loads on a recreational boat steering system and, secondly, to document the maximum loads that may result under extreme maneuvering conditions or misadjusted geometry.

4.2 Results

4.2.1 BAR Files and Defect Campaigns

Of the defect campaigns that existed at the time of project initiation and those that occurred since then, very few were related to design oriented problems. Of the 24 campaigns investigated, only seven were remotely connected with design defects that a performance oriented standard would address. The vast majority of these defects resulted from poor dealer/manufacturer communications and quality control procedures. Additionally, over the past four years, according to the BAR files, a total of approximately 250 accidents have been attributed to steering system failures resulting in approximately 36 deaths and over \$60 thousand in property damage. The amount of information, or lack of it, in Coast Guard Headquarters boating accident report files made it extremely difficult to document cases of clear-cut design deficiencies. (Appendix A contains a summary of the defect campaigns underway during this study.)

4.2.2 Warranty and Liability Claim Files

Results of discussions with industry concerning the review of warranty and liability claim files were inconclusive in identi-

fying the exact hazards that exist. Warranty files, as a general rule, for steering systems are minimal. This is due to the fact that there is an extremely low percentage of return of warranty cards on accessory equipment. (One company estimated their return at 0.1%.) As for liability files, the manufacturers are very cautious as to what information is released and therefore it probably does not reflect the entire picture. Those cases that were mentioned were not of a design oriented nature. It is unfortunate that these cases which are mainly improper installation or part substitution, lack of maintenance, or operator misuse are not verified by court decisions. Each manufacturer, without exception, indicated very few, if any, of the liability cases ever go to trial. For economic and publicity reasons most are settled out of court.

4.2.3 Accident Investigations and Field Survey

During the work, enough information was collected to adequately document five accidents in addition to the nine systems which were collected during the field survey. A brief description of this is given below.

PROBLEM	NUMBER
Circumferential cracking of cable outer cover and subsequent corrosion of wire conduit near output end.	s and analysis of and and a substitution of a su
Corrosion of ball joint and ball stud severe enough to prevent relative motion of the joint.	(2015) (2011 302) 3 85-98
System frozen at output end from corrosion, salt/dirt buildup. Failure in helm assembly from excessive torque in wheel.	3 062-08 98/ 02 go una
Broken steering rod caused by engine striking submerged object and being thrown to full tilt position.	1
Steering rod failure due to stress corrosion cracking through thread root internal to rod end connection.	1
Loss of steering due to cable hub nut vibrating and backing off.	352-019 . 1
Improper tension in cable over pulley system caused cable to jump off helm assembly drum.	00 j - 00 1

The above cases compared favorably with the recommendations of marine mechanic interviews. These problems were:

a. The need for adequate preventive maintenance (periodic lubrication and visual inspection).

b. The need for better anti-corrosion protection of exposed steering parts.

- c. The need for standardization of parts and improved installation instructions to eliminate improper installations and part substitutions.
- d. The need for lubrication seals, especially on steering cable rods, support tubes, and engine tilt tubes.
- e. The need for improved lubricants to aid in preventing the hardening up and "freezing" of a system due to salt and dirt buildup.

Appendix B presents the requirements for the proper documentation of recreational boat steering and control systems as was developed within the framework of this study. It is intended to serve as a guideline for future hazard/problem identification and accident investigation efforts.

Appendix C presents further information concerning the field survey and marine mechanic interviews.

4.2.4 Instrumented Boat Tests

Instrumented boat tests were conducted by R&DC and three industry manufacturers. The range of loads typical to single engine outboards corresponding to the maneuvers involved are shown below. The loads are all given in pounds force normal to the motor tiller arm and in the plane of motion of the tiller arm.

AVERAGE LOAD (1bs)	MANEUVER
30–50	Normal operation in smooth water; no drastic maneuvers.
80-150 w/peaks up to 180	Quick acceleration DIW to full throttle with full motor angle; changing direction of turn while accelerating; tight turns and figure 8's in 6" to 1' chop.
200–300	Tight turns at approximately 20 MPH in 2' seas; striking submerged object throwing motor out of water.
200-250	Impact loads from propeller re-entry with 0° motor angle.
400–430	Impact loads from propeller re-entry with starboard motor angle and port yaw on boat or vice versa.

Steering wheel torques for the above maneuvers varied between 3 and 9 foot pounds. Assuming a 15-inch diameter wheel these loads translate to approximately 5 to 15 pounds wheel effort, which is well within an operator's normal capability. The highest wheel torque in any of the testing was 24 foot pounds (38.4 lb. wheel effort). This was recorded on a reentry with the

exposed scenting carts.

boat in a port yaw attitude with starboard motor angle. Additionally, it was found that lower unit trim tab and engine tilt setting have a significant effect on steering loads. Steering arm loads have been found to vary in RMS average as much as 100 pounds due to misalignment of the trim tab. The tilt setting will alter steering loads and wheel torques since this setting controls the amount of underwater hull form of the boat. Each individual boat/motor combination must be "water tested" to insure optimum adjustment.

Figures 1 through 4 show sample plots of the data from some of these typical maneuvers. In Figure 1 the steering load measured normal to the motor tiller arm is shown during accelerated turns. In this maneuver the boat is "dead in the water" with full motor angle and then full throttle is suddenly applied. Due to propeller cavitation this condition can be maintained for only the short durations shown. On a typical recreational boat steering installation, the high tensile loads are placed on the steering rod when it is extended (i.e. starboard motor angle) and the compressive loads occur on the retracted rod. It is important to note that the system design and geometry prevents a more critical condition from occurring (i.e. compressive loads placed upon an extended steering rod).

Figure 2 shows a comparison of the steering loads which exist during a straight course acceleration from zero to full speed with optimum and misadjusted lower unit trim tab setting. In the upper tract the effect of the transition to planing mode is evidenced by the reversal of steering loads as the wetted surface and hull forces change. The lower trace shows that the trim tab setting can account for upwards of a 100-pound increase causing the boat, in this case, to pull violently to starboard.

Figure 3 is included to show the importance of the trim tab to balance the torque produced by the outboard. With no trim tab installed and the boat being operated in a "hands off" condition the motor angle is shown to continuously drift off center. While at steady state speeds this change in motor angle is relatively slow, it could be more drastic under conditions of quick acceleration or rough water conditions.

Figure 4 shows traces of boat speed, engine rpm, and steering load which were recorded when the lower unit of the outboard struck a submerged object causing the propeller to be thrown out of the water. As may be seen from the time reference, at the point of contact, the rise in steering load is accompanied by a reduction in boat speed and a significant increase in engine rpm. The twin peak in the rpm trace is in all likelihood a false reading resulting from an interference signal caused by the closing of the engine kill switch circuit.

5.0 INDUSTRY SYSTEM TESTS

In order to document the efficiency, effectiveness, and reliability of current production steering systems various industry tests were conducted under requests from the R&DC and/or the BIA Steering Task Force.




Figure 1. Steering Load Traces from Full Motor Angle Accelerated Turns

bellebile eith kepel withhel avoi






Figure 2. Steering Load Traces Showing Effect of Trim Tab Adjustment





Speed, RPM, Steering Load Traces While Striking Submerged Object

5.1 Laboratory Cyclic Tests

The tests performed in the laboratory were input torque-output load tests and life cycle tests. The input torque-output load test is run under a standard "as installed" setup with 270° total cable bend with 10-inch bend radii. The output end of the system is placed under a constant load and the system is cycled by inputing torque to the helm assembly. Information received from this test includes system efficiency, ultimate failure load, ease of operation, and system backlash.

5.1.1 Rotary and Rack and Pinion Systems

The efficiency of current production mechanical push-pull systems, over the range of loads examined, averaged 50.4 percent in the pull mode and 41.4 percent when pushing.

All systems failed when in the push mode at an average output load of 590 pounds corresponding to an average input torque of 59.8 foot pounds.


The average ease of operation of the systems tested was 1.38 foot pounds or a 2.2 pound wheel effort (assuming a 15-inch wheel). Ease of operation is defined as the amount of torque applied to the steering wheel necessary to cause movement of the output end.

The average backlash of the systems was 14.1° and 23.5° under a 25 in. 1b. and 50 in. 1b. wheel torque respectively with the output end locked.

5.1.2 Stick Systems

The above discussion and average values do not include those associated with "stick steering" systems. Due to the nature of application of stick systems their characteristics depart drastically from the conventional rotary or rack and pinion system. Stick steering systems generally exhibit efficiency in the neighborhood of 38 percent pulling and 29 percent pushing. Also, due to their lower mechanical advantage they are harder to operate (8.5 ft. lb.) and exhibit lower backlash figures. (1.1° @ 25 in. lb. and 6.6° @ 40 in. lb.). Ultimate failure output loads were of the order of 150 lb. corresponding to an input torque of 26 ft. lbs. The quick motor response and relatively low strength of these systems make them an excellent candidate for a limited application recommendation. The proposed ABYC P-17 standard makes no attempt at singling out specific standards for stick steerers. Therefore, these systems will have to meet the same strength requirements as the conventional mechanical push-pull systems.

Figure 5 shows the efficiency envelopes of the steering systems tested in this program. Since the specific data is proprietary to industry, it is presented to show the range of values that may be expected with current systems. Envelopes are shown for both the pulling and pushing mode versus a constant load applied to the output end of the system. As expected, systems are on the average 15-20 percent more efficient when pulling as compared to pushing. The system efficiency as used here is determined from the following formula:



 $\eta = \frac{kdF_0}{\Theta Q_1}$

where

d = cable travel in inches

Fo = output load in pounds

 θ = degrees of helm rotation

Qi = helm input torque in foot pounds

k = constant (4.77)

Figure 6 presents this data in terms of the input or helm assembly torque required to operate the steering system given a certain output load level. From the above equation it is seen that the system's efficiency is proportional to the slope of the envelopes shown in Figure 6.

Figure 7 presents an idea of the amount of backlash present in the representative steering systems. These backlash envelopes are plotted versus the input torque applied. This input torque is that required to cycle the system under the corresponding output load from Figure 6. Having completed the "pull stroke" of the cycle, backlash may be thought of as the amount of helm rotation that takes place prior to the initiation (actual movement of the steering rod) of the push stroke.

5.1.3 Fatigue Tests

The laboratory fatigue tests indicate that the fatigue life of current systems runs approximately 186,000 to 200,000 cycles on the average under a constant 50 lb. output load. The fatigue life under 100 and 200 pound output loads drops to 100,000 to 120,000 cycles and approximately 50,000 cycles respectively. The most important parameters affecting fatigue life are cable bend radius, total degrees of bend, and proper lubrication. Note that these figures represent full cycles under a constant load as compared with the partial cycles and loads of short duration in the field. The laboratory fatigue lives are based on much more severe conditions than can be expected to be encountered in the field. Thus, current systems as manufactured are judged to have more than adequate fatigue strength.


5.2 Other Industry Tests


Other industry tests carried out at the R&DC's and/or BIA Task Force's request addressed such areas as:

- a. Cyclic corrosion testing of steering system output ends.
- b. Cyclic (fatigue and thermal) and impact tests of steering wheels.
- c. Static deflection tests on motorwell sidewall mounts and transom brackets.
- d. Static deflection tests of steering system output ends.

5.2.1 Cyclic Corrosion Testing

During this work some preliminary corrosion tests were conducted by the industry in order to aid the BIA Task Force in developing





a corrosion test program for outboard steering systems. Although specific results are not given here, the industry has demonstrated its capability to produce a steering system able to withstand this test and retain its original function. That is, efficiency, backlash, and amount of travel do not depart from their original design values. Basically, the corrosion test procedure involves pre-test ultraviolet exposure of the output end (including cable sheathing and seals) of the steering system. Followed by a cyclic salt spray test. The latter is conducted in accordance with ASTM B 117-73 (ANSI Z118.1) Standard Method of Salt Spray (Fog) Testing.

Notwithstanding the above discussion, there still remains some concern among industry with respect to the proposed test. It is felt that the evaluation of test results listed in Section P-17.8C.(2) of Appendix D leaves too much interpretation to the evaluator. Thus, the industry feels that problems could arise. As an example, a strict interpretation could fail a system utilizing a stainless steel output ram due to no more than "cosmetic" corrosion while a liberal interpretation could allow a weaker system; i.e. cadmium-plated carbon steel ram, to pass the test.

The current ABYC P-17 standard is scheduled to become effective in August of 1977. As a result, there is a strong possibility that prior to this standard taking effect, the corrosion test itself, along with the evaluation of test results, will be revised. Current plans call for the revision to be more strict. This will be accomplished, in all likelihood, by increasing the number of exposure hours in the salt spray chamber. By utilizing a stricter requirement the interpretive element is removed from the test result evaluation.

5.2.2 Steering Wheel Tests

Some testing has been performed on "insertless" plastic steering wheels. Although the data is again proprietary, the following summary is provided. Current insertless wheels seem to have no problem in passing combined torsion and bending cyclic tests adapted from the automotive industry. All wheels withstood in excess of 50,000 cycles of fatigue testing without failure. The same may be said for static deflection tests conducted under a load of 150 pounds at sub-zero temperatures. Under the 200 foot-pound impact test (Appendix D) all wheels suffered some damage. The extent of this damage varied from only minor blushes to complete shattering of the spoke and rim. The wheels underwent two additional tests. First, 15 complete alternating cycles of 150 to 160 pound axial loading and second, three thermal cycles of -40°F to 180°F. After both of these tests the wheels were tested to destruction statically. In all cases, the wheels failed at load levels higher than the previously mentioned 150 pound static deflection test.

5.2.3 Static Deflection Tests on Motorwell Sidewall Mounts and Transom Brackets

At the request of the BIA Task Force a series of tests were conducted to investigate the strength of steering system anchorages attached to boats. Basically there are two types of boat mounted steering systems. The steering cable is anchored to the boat either by passing it

through a transom bracket mounted to the transom or a gimbal mount connected directly to the motorwell sidewall. These are shown in Figure 3 of Appendix D. The proposed industry standard, developed by the BIA Task force requires an "as installed" test which places 750 pounds along the axis of the output steering ram. Since this is an "as installed" test the mounting devices must also withstand these loads. Both the sidewall and transom-mounted systems were tested and included products from a wide range of manufacturers. In summary, all anchorages were found to be adequate for sustaining the 750-pound load without failure or structural damage. In general, the motorwell sidewall mounts will withstand higher load levels and display smaller deflections. With transom-mounted systems, it was discovered that a good amount of deflection can result from crushing of the transom plywood rather than bending of the bracket itself.

5.2.4 Static Deflection Tests of Steering System Output Ends

These tests were conducted as part of the work conducted by Outboard Marine Corporation under contract to the R&D Center. Since this report is shown in its entirety in Appendix E, only a brief summary is discussed here. The static tests were structured so as to define the steering system geometry that would place a maximum load on the member of the system that will fail initially under increasing loads. Critical deflections were measured under various loads to determine the level of loading that causes the onset of permanent deflection and that which causes failure of the system to function throughout its normal range. Whenever possible, the systems were misadjusted to ascertain the worst possible condition.

It should be noted that Appendix E also contains dynamic tests conducted with instrumented boats. These tests were designed to measure the steering loads under the most severe conditions such as wave jumping with high speed prop reentry and high speed turns including total spinouts. In anticipation of future work these tests were conducted with twin outboard, single I/O, and twin I/O powered craft.

5.3 Comparison to ABYC P-17 Standard

Whereas the systems tested proved effective in meeting the strength requirements established by operational tests there are several areas which will need improvement in order for them to meet all requirements of the proposed ABYC P-17 standard. These are:

- a. Corrosion of ball joints, drag links and support brackets.
- b. Fractures of "insertless" steering wheels under impact and thermal cycling.
 - c. Deflection of drag links under static deflection tests.
 - d. Excessive deflection in transom-mounted bracket systems.

The P-17 Standard is shown in Appendix D.

6.0 CONCLUSIONS

The primary conclusions of this work are:

- a. The loads experienced by a recreational boat steering system for single engine outboards equipped with mechanical push-pull systems are not considered excessive.
- b. Current systems are of adequate efficiency, effectiveness and reliability to meet these loads if properly installed and maintained.
- c. The industry has demonstrated its capability to self regulate. The proposed ABYC P-17 standard developed by the BIA Steering Task Force addresses the correct problems and sets realistic strength requirements from a safety standpoint.
- d. The predominant problems with recreational boat steering systems result from lack of preventive maintenance, improper lubrication, improper installations because of non-standardized parts and/or sufficient installation instructions, and environmental degradation from salt water and ultraviolet exposure.
- e. The number of lives lost and level of property damage documented in Coast Guard BAR files is insufficient to justify a need for a Federal standard for outboard steering systems.

7.0 RECOMMENDATIONS

Therefore, the following recommendations are made:

- a. That there is no necessity to develop a Federal safety standard for mechanical push-pull steering systems now used with single outboard engine recreational boats at this time.
- b. That the Coast Guard strongly encourage the industry's compliance to the proposed ABYC P-17 standard in that ABYC P-17 standardizes parts, provides for corrosion protection, and establishes strength requirements which are realistic.
- c. That the Coast Guard, through the use of the Boating Safety Circular and educational efforts stress the importance of such areas as:
- (1) Proper lubrication and preventive maintenance (especially at the beginning of the boating season).
- (2) The need for improved, clearly defined installation instructions.
- (3) The use of self-locking threaded fasteners in critical points of the steering system.
- (4) The importance of proper lower unit trim tab and engine tilt adjustment.

- d. That the Coast Guard be aware that, upon publishing of the ABYC P-17 standard, there is a three-year compliance period. Care will have to be taken so as not to compound the non-standardization problems as engine, steering system, and accessory manufacturers make their change-overs. The Coast Guard must also be aware that this is a voluntary program on the part of the industry. The proposed ABYC P-17 standard is slated to take effect in August of 1977. This same P-17 standard has been adopted by the BIA as part of its 1977 BIA Certification Handbook which takes effect August 1976. (NOTE: Due to the likelihood that the corrosion test section of the P-17 standard will be revised, this portion will be "advisory only" for BIA certification until August of 1977.)
- e. That the Coast Guard remain active in its particupation with the BIA Task Force as it progresses to twin outboard, I/O, and cable-over-pulley systems.

18

provides for tournaise profession, and setablishes excepts significants

of the beginsted of the Boating and in

REFERENCES

- Boating Industry Association (BIA) Steering Task Force Meetings, various minutes and memoranda.
- Boating Statistics (CG-357), U. S. Coast Guard, 1970, 1971, 1972, 1973.
- Miller, James M., Human Factors Application in Boating Safety, The University of Michigan, Ann Arbor, MI, September 1973.
- Plantec, Peter, Findings From a Survey of Marine Mechanics Regarding Steering System Failures, Operations Research, Inc., Silver Spring, MD, October 1974.
- Steering Malfunctions, 1972, A Study of Boat Accident Report Data for the Boating Standards Division, Office of Boating Safety, U. S. Coast Guard.

APPENDIX A

STEERING AND CONTROL SYSTEM DEFECT NOTIFICATION CAMPAIGN SUMMARY STEERING SYSTEM DEFECTS*

DESIGN RELATED

- a. Mechanical push-pull steering with inboard-outboard engine. Apparently the ball joint used to connect steering rod to outdrive fails after a few weeks in service. There was some uncertainty as to the actual problem and cause; however, salt water corrosion was a strong possibility.
- b. An aluminum steering bracket manufactured for I/O installation was felt to be questionable in its ability to hold up under turning loads. At the time of investigation the bracket was being replaced with cadmium steel.
- c. Hydraulic push-pull steering system for use on I/O installation. Steering arm between the hydraulic cylinder and outdrive tiller arm unscrews. Easily remedied by means of a pin.
- d. Steering yoke failures on twin V-8 I/O installations. This failure occurred on twin installations only and at high speeds (45+ mph). Was attributed to the high impact loadings placed on the steering system when the propellers reenter the water after having been airborne. New parts were made utilizing stainless steel to provide more strength. Also addressed was a speed governor to limit propeller rpm.
- e. Continuation of (d) above. This time the steering arm was suspected and, although there were no failures, it was replaced by a stronger unit.

OTHER THAN DESIGN RELATED

- f. Mechanical push-pull system for 65HP outboard. In this installation the dealer must cut the transom well hole and place the transom bracket in the proper location. As the hole location varies with the boat no template is provided as an installation guide. The installer misplaced the bracket thereby causing a bending load to be placed on the stainless shank at the outer cable hub when the engine is tilted.
- g. The steering lever on certain I/O installations became loose after a period of service. Cause attributed to lack of quality control in that steering lever fasteners were not properly torqued.
- h. Mechanical push-pull steering on certain I/O installations. The steering system manufacturer provides a jam nut with the ball joint connection kit. The I/O manufacturer supplies a special extension adaptor to be used in lieu of the jam nut. In order to provide adequate strength in the connection the extension adaptor must be threaded until bottomed. Due to a mix-up in instruction bulletins, the jam nuts were not being removed prior to installation of extension adaptor. This left the adaptor only partially threaded causing a high probability of failure at the fitting.

^{*}Specific manufacturer names (i.e., steering system, boat, and engine) have been omitted.

- i. Mechanical push-pull stick steering system. The steering this installation is held in place by means of a clamping bolt. The color could not be overtorqued due to a designed thread failure. The bosupplier changed to a higher grade bolt without steering manufacturers knowledge. Results were that bolt could now be overtorqued causing hub failure and subsequent loss of steering.
- j. Transom bracket mount for mechanical push-pull system. The boat manufacturer in this case fastened the mounting bracket to the transom wit lag screws. The screws were too short and would pull out of the transom. The manufacturer subsequently replaced with longer lag screws. (Note: It would appear that thru-bolting would have been a much better solution.)
- k. Steering arm-engine connection. In this case the boat manufacture installed the clevis bolt upside down. This is the bolt that connects the steering output arm to the motor tiller arm. Vibration would cause the nut to loosen, back off and fall in the bilge causing a potentially hazardous situation.
 - Mechanical push-pull steering. Steering cable had

neighbors that all common the transport of the contract of the

then of the jew tool is order to provide adoptate strongth in the consection to extremely described in a player in interest of the last too payers in interest of the jew some work with bride received prior to installation to conserve the last the shapes will be according to the conserve the same of the conserve the conserve the conserve the conserver of the conserver the conserver of the conserver the conserver of the conserver

(anthrop home , hard preserve greeners, a.) uness territorings and charge

- e. Outboard motor throttle control. This is a single case and was somewhat unclear as the investigation was still on-going. The problem was that the motor would stick at wide open throttle. There was evidence, however, of owner abuse in that the engine would be placed in gear at a high rpm causing jamming problems with the clutch dogs.
- f. Throttle cable. This was a clear case of improper installation. The throttle cable was installed with a 45° bend (included angle) at the control head and another 45° bend at the motor connection. This led to excessive force required to effect throttle changes.
- g. Jet drive. In this case the reverse gate pivot pin bolts were insufficiently torqued causing improper operation of the gate.
- h. Outboard motor shift rod assembly. The motor manufacturer was obtaining shift rod hydraulic plungers from five different vendors. One vendor was supplying these plungers with improper machine grooves resulting in shift problems.
- i. Motor control head. This again was a single case occurrence. It involved a report of excessive binding in the control head making throttle and shift operation difficult. Result was that the binding was due to excessively tight adjustment on the control head friction adjustment. Simply backing off on the friction adjustment solved the problem.

APPENDIX B

REQUIREMENTS FOR THE DOCUMENTATION OF RECREATIONAL BOAT STEERING AND CONTROL SYSTEMS

1.0 PERSONAL INTERVIEWS

This section covers the usage and history of the involved system and is primarily aimed at the boat owner/operator to document his particular boating environment before, during and after any associated problems. However, certain pieces of information in this section may be answered more readily by the mechanic or, in some cases, the interviewer.

1.1 Usage and History

-	•	+	•	-	<u>U</u>	94	ge
					1	303	270

Adizona line

1.1.1	Usage not all arent beautile required
	Age of boat, engine, system years Estimated hours of operation
	Description of environment normally operated in.
	What is boat used for: Cruising
	Fishing
	Utility
	Skiing
	Racing
	Other
	What is maximum speed capability mph
	How often at full throttle operation %
1.1.2	History have full machine and maliation with the
	Type 1 2228 Sur advices the Line survey of the term
	Circumstances prior to failure: loading, speed, maneuver, sea conditions, weather conditions, etc. Any warning of impending failure Yes No If so, how manifested? Were there previous problems of same nature? Reaction of occupants and boat at time of failure. What components failed? How? Why? Photos and documentation.
	Type 2 -
	What prompted owner to seek correction?
用户数据	Circumstances at time of discovery of problem.
	Were there previous problems of same nature?
100% 数	Capability of system after problem:
	Limited travel in both directions
	Limited travel to port starboard
	Increased wheel or control effort
	Squark or notes in evetem
	Sloppy (excessive backlash) Limited throttle range
	Limited throttle range
	Limited shift control to fwd back only
	#-1

	What was the identified	problem? What co	omponents involved?	
	What caused the problem			
	Improper design			
	Insufficient st	rength		
	Improper instal	ation		
	Excessive loads			
	Misuse			
	Excessive use (normal wear)		
	Corrosion			
	Improper mainten	nance		
	How remedied?		officer transported with	
		ARCH TRANSPORTS TO STREET AND THE PARTY OF T		
	Type 3 -			
	What component(s) appear	suspect? Why?	I.l Usaga and Hick	
	COLLOSION OI IM	icrional antiaces		
	Bent or deformed	components		
	Improper/altered	installation		
	Mismatched syste	ms		
	Age of system	oet, engeln, sty of hours or effects close of sustrouse		
	Other (specify)			
	Comments:	To the author		
	2.2 is aimed primarily			
1.2 <u>Pra</u>	actices and Procedures.	Questions to be	answered include:	
1)	Are installation instr they clear and specifi	uctions always av	vailable? If so, are	
2)			1.1.2 History	
3)		uctions rollowed?	To what degree?	
4)		cutouts and acce	sas notes focated;	
5)			1-1-1	
6)	이 있는 것이 없는 사람들이 되었다. 이 이 바로 가장 이 가장 사람들이 없는 것이 없다면 없다.	nce tested upon i	nstallation? (T.e.	
	motor arc, engine trim	tab, engine tilt	. positon, etc.)	
7)	What amount of systems	are returned to	manufacturer? Why	
	warranty, overstock, e	tc.	,	
8)			complaints concernin	
	steering and control s	ystems and what a	re their causes?	-
	Failure/problem	celralmanabb bee	Photos	
	1., etc.		Type 2	
0)	Toolinganing dee	a of Tanyo Dadome	What us	
9)		ng to keep a runn	ing total of his	
10)	answer to question 8 o	ver a period of t	ine (
10)	Is there a definite co	LIETETION DETWEEN	steering and control	
	problems and specific	muracturers? I	I so, What?	
DYRON	e port star	Limited teavel t		
	240170 /01/400 40			

pack only

Limited shift control so

2.0 SURVEY DOCUMENTATION

This section covers in detail the documentation required for a complete analysis of the boat/engine/steering and control systems. While it is anticipated that every sampled system under investigation will not allow completion of all the following, every effort should be made to complete as much as possible from the various sources available. The information is broken down in four categories. These are:

- 2.1 Boat
- 2.2 Engine
- 2.3 Steering System
- 2.4 Control System

2.	4	Roat	ě.
4 -		NOA!	п

2.

1	Boat			
	Mfg	Model	Yr Mfg	HIN
	Length	Beam	Weight	an landon's 6A
	Type:	Outboard	1/0	Jet
	Hull form:	Deep Vee	Semi-Vee	Tri-Hull
		Flat Bottom	Round Botto	mTunnel
		Pontoon	Other	
	Hull mater	ial: Fibergl	assAluminum	WoodOthe
	Transom cu	tout: Yes No	No semanti de	
	Motorwell:	Yes No	A Company of the Comp	
	Certificat	ion: BIA	_Mfg compliance	label
	Max Hr	Max Wt Cap	Max persons cap	
	Transom	height Trans	om thickness	170
	Motorwel	1 width Tran	som angle	ant.
	Dimensiona	1 sketch of stern	including transom	cutout and motorwel
	also showi	ng size and location	on of motorwell a	ccess holes.
) Bow		
) Stern		
	3) Profile	0.47017	
	29/48/9500 \$) Overhead, looki	ng forward	
	tanent re) Overhead, lookis) Overhead, lookis) Others as deeme	ng aft	
	0) Others as deeme	d necessary	
2	Engine			
	Mfg	Model	Serial #	
	Yr mfg	Mfg HP_	Weight	1b
	2.2.1 Out	boards		
	Pow	er trim/tilt:	Yes No	
	# 0	f tilt pin position	ns Position	being used
				Yes No
	Twi	gle engine centere n engine centerlin motor angle	e spacing	
	Max	motor angle	Stbd Port	
	Eng	ine attachment	Tiller arm	
	If	tiller arm has two	holes, which is	being used for
		steering:fo		
	Til	ler arm radius	in.	
	Dim	ensional location	of tilt pin or ti	
		reference to top f	wd corner of tran	som and boat
		centerline.		

	2.2	1.2	Inboard/	Outboard	or Je	t
--	-----	-----	----------	----------	-------	---

Drive Mfg	Model	Serial #
Power trim/tilt:	Yes No	na Maray (1990) in the little of the
Drive attachment:	Tiller arm	Thru transom
	Worm gear	completion of all one that
Max drive angle:	Stbd °P	ort it sidisacq as doom a
Photo documentation	n as necessary.	s byolum Bown in love on

L.I Boat

2.3 Steering System

The recreational boat mechanical steering system can be broken into four categories:

- 1) Steering wheel
- 2) Helm assembly
- 3) Cable assembly and integral fittings
- 4) Engine connection kit

2.3.1 Steering Wheel

Mfg	Model		
Diameter	Inserted:	Yes	No
Hub attachment:	Round taperSpline	Square	taper
Total rotation s		and the said	(450)
Inspect for crac	ks; deformation; in cols; excessive stee	terference ring effort	with boat, ; and proper

2.3.2 Helm Assembly to a hard specific state of the state


Mfg

Type:	Rotary	Rack and	pinion		
	Single	Dual	Control (4		
Inspect f	or corresion,	excessive	backlash,	excessive	endplay
tightn	ess of cable	attachment	nut, prop	er install	ation.

2.3.3 Cable Assembly and Integral Fittings

Model |

Mfg	Туре	Cable length ft
Total degrees	of bend	5 1908 S
Cable radii	in. at helm	is the state of
	in. at transom	
	in. at (other,	specify)
Max cable tra		
Diagram of ro	uting showing meas	surements for cable length.



Inspect cable for corrosion of end fittings and steering rod; evidence of moisture or lack of lubrication; permanent deflection of steering rod; cuts, gouges, or other damage to cable; proper installation.

2.3.4	Engine Connection Kit			
	Mfg	Trapect for excessive force to ented autemone, excidence		
	Type:	Engine mounted (thru tilt pin)		
		Boat mountedTransom bracket		
		Splash well mount		
	2.3.4.1	For boat mounted:		
		Location of transom bracket or splash well mount pivot point:		
		 a) Distance from engine centerline to pivotin. b) Distance of pivot fwd of transomin. 		
		c) Height of pivot above or below transom in. Total degree of articulation in pivot		
		Inspect cable hub nut attachment to transom support		
		tube for tightness and corrosion. Inspect transom support tube for interference-free pivoting.		
		Inspect seals for cracks, aging effects, etc.		
		Type of engine attachment:		
		Quick release ball joint and ball stud		
		Ball joint with threaded fastenerIntegral ball joint/stud Clevis		
		If dual installation, is there a tie bar?YesNo		
	2.3.4.2	For engine mounted (thru tilt pin):		
		Inspect cable hub nut attachment to engine for tightness and evidence of corrosion.		
		Total steering rod extensionin.		
		Type of drag link steering rod connection:		
		Thru steering rod hole		
		Thru threaded connector		
		Type of engine attachment: Quick release ball joint and ball stud		
		Ball joint with threaded fastener		
		Integral ball joint/stud		
		If dual installation, is there a tie bar?YesNo		
	2.3.4.3	For both types of mount:		
		Inspect system for interference throughout the entire		
		steering arc in both the run and tilt positions.		
		Inspect connection kit for compliance with installa-		

tion procedures.

Mfg		nos , edno	ther pakt	inade de ac	deflecti	
Cable lengt				r proper (c	31060 03	
Single leve	ear protection:	Yes	No	l nationaus	O ealgne 4	
Inspect for	excessive for	e to effec	t moveme	nt, evidend	e of bindin	ıg.
integrity o	of cable fitting	gs and atta	chments,	and corros	sion.	-6,
Inspect for	interference v	with steeri	ng wheel	, boat, or	driver.	
	cable routing amply with recomme					
DOES IT COL	uply with recomm	nended Inst	attation	practices	Yes _	1
			: basenor	r dand tox	1.4.6.1	
*m 7.						
				tied javid		
				Malwe (a		
				is nous		
				Inspect		
				piwoth		
		y amesaica.				
				1		
				t lamb 11		
				alone not	2,3,5,2	
				Inspect c		
				Cigina		
			ide entga	Type of e		
	lied the only					
		lamber Lie	Largade Elasí	The latest test and the latest test to be a second		
	frad 513 a aus	sit #1 .nul				
			in secur	For both	2.3.4.3	
	Junkiponski nade Teog Ilka bos s					
watturmer	dika epastigan	and and and		STANDAR		
				tion proc		

APPENDIX C

EXCERPTS FROM "FINDINGS FROM A SURVEY OF MARINE MECHANICS REGARDING STEERING SYSTEM FAILURES"

It must be borne in mind that much of the information in this appendix comes from direct interviews with marine mechanics. The views and opinions included are those of the mechanics only. References to specific manufacturers of brand names have been deleted.

PURPOSE

This survey is a study of the nature and types of steering failures in two categories of power boats:

- 1. Outboard motor boats
- 2. Inboard/outboard motor boats

More specifically, the survey attempts to indicate if the relationship between steering failures and boating accidents is significant enough to warrant further research.

PROCEDURES off many about ad her become realist and had and le address AC and le address AC

There are two parts to the survey: (1) interviews with 34 boat mechanics and (2) the collection of 50 defective steering systems. The scope of the survey is limited primarily to marinas, dealers, and service centers in the Baltimore-Washington-Annapolis area with several interviews in Miami, Florida, presented separately. Interviews were conducted during the second week in May, the last week in July and the first week in August, 1974.

Several interview techniques were used which required probing for depth of answers. Probes were used with the utmost care to avoid leading the respondent. In some cases unobtrusive measures were used, such as stimulating a conversation about steering mechanisms between two mechanics and then recording the relevant output. In general the interviews were low profile, informal affairs, designed to fit into the mechanic's routine as much as possible. Coast Guard involvement was not emphasized, nor was it hidden.

I. CLASSIFICATION OF STEERING SYSTEMS

Defective systems have been classified into one of the following types:

Type I: System failure has already occurred leaving the system inoperative unless repaired or replaced.

Type II: System which has some type of damage or wear leading to a reduction in original capability, but which still operates in a limited capacity (e.g., customer complaints of "squeaks" or "hard steering").

Type III: System which has not failed nor prompted owner to seek correction but nevertheless appears suspect for various reasons (e.g., corrosion of functional surfaces, bent or deformed components, improper or altered installation, mismatched systems, excessive age or use).

Each defective system was to be further documented by interviews with the owners of the boats and with the mechanics who replaced or repaired the system. These interviews focus on the circumstances of the failure or partial failure of the system.

In addition to the interviews concerned with specific instances of failure, more general interviews with mechanics were also undertaken. Specific questions were asked during interviews but the responses and format were open-ended. These interviews had the flavor of informal discussions with mechanics, designed to elicit information about steering systems. For example, in some instances responses were recorded after the interview was completed, in order to keep the anxiety level of the mechanics at a minimum.

II. COMPILATION OF RESPONSES FROM MECHANIC INTERVIEWS AND SAMPLE ANSWERS

A profile of the 34 mechanics interviewed can be made from the responses given to Questions 3-5 on the Mechanic Interview Questionnaire. The responses given to Questions 6-10 were all nearly the same and therefore a breakdown of answers is not given. Instead, representative responses from the questionnaire are quoted. Questions 1 and 2, Name and Place of Employment, are not included.

Question 3 - Years of Experience

Years of experience ranged from 2 years to 30 years. A breakdown of mechanic experience follows:

Years of Experience	No. c	f Mechanics
weathanter and then		16
6-10	ratni eda inter	4
11-15		3
16-20		7
21-30		4
	Total	34

Question 4 - What percentage of small boat repairs that you do is concerned with steering mechanisms?

The most frequently given answer to this question was less than one percent. One answer given, "Ten percent in April and May," is rather hard to interpret since the respondent did not answer the question in its entirety. For the tally purpose, this answer will not be counted.

Percentage of Steering Repairs	No. of Mechanics
Less than 1%	29
Less than 5%	1
5%	1
No answer	2
	Total 33

Question 5 - How many steering mechanisms do you repair in the course of a year?

The answers to this question ranged from "none in past year" to "50." The breakdown is shown below.

No. of Repairs	No.	of Med	hanics
1-5		20	
6-10		6	
11-15		1	
16-20		1	
21-30		3	
40-50		2	
None in past year		1	
BUTTON HOTE THINK ME	Total	34	

Question 6 - Do you know of any steering failures that caused accidents or near accidents? If yes, what are the details.

Only three mechanics answered yes to this question. All other 31 respondents answered no. Of those three who answered yes, no in-depth details were given. The answers are listed below.

"Tiller system failed - boat capsized - no one hurt."

"Loss of steering but no accident. Boat sustained minor damage. The quick couple on the post broke."

"Tiller arm pin sheared off leading to an accident."

Question 7 - Are there any systems which seem to have significantly more problems than others?

"Tiller type cable systems which use pulleys are the least satisfactory - pulley comes loose - cables twist - cables seem to rust up quicker."

"All systems OK when properly maintained. Mechanical systems better than tiller on boats over 40 h.p."

"Mechanical systems are the best. Old tiller type more prone to rust, twisted cable or broken cable. No good on boats over 40 h.p. anyway."

"Cable systems have more problems than telescopic systems."

Question 8 - Describe specific types of steering mechanism failures that you are familiar with.

"Most failures result from corrosion of components and rust, twisted cables, cables that are too long. Trim tab adjustments also account for failures."

"The most frequent type of failure occurs at the beginning of the boating season. The stern end of the cable freezes up due to rust and corrosion. All other types of failures are extremely rare."

"Tiller type systems - cables rust or snap. They can snap if they are twisted and this could lead to an accident. Mechanical steering freezes up from rust caused by lack of lubrication."

Question 9 - What improvements could be made in steering mechanisms to reduce the probability of failure?

"Reroute cable so it stays away from manifold."

"More grease fittings on cable, the use of non-corrosive material for cables. All steering arms should be brass or stainless steel, tighter seals to prevent water from getting inside cables."

"The use of brass or stainless steel components where corrosion is a factor, i.e., ball joints and telescopic units - better seals. All systems work well if properly installed and adjusted, and maintained.

Question 10 - Are there any problems installing systems?

"Improperly designed transom makes steering hookup difficult. Some standardization of parts needed."

"Replacement of system could be made easier if accessibility to cables were better. Cables are frequently embedded in styrofoam making replacement difficult and sometimes results in poor installation because cable tension is not proper."

"Difficult to get proper parts. Manufacturer often makes improper substitutions, i.e., smaller gauge cables - cables that are too long."

III. SUMMARY OF MIAMI, FLORIDA, INTERVIEWS

Sixteen marina mechanics were interviewed at widely spaced locations in the Miami, Key Biscayne area. The questions asked follow, with a discussion of responses:

1. Do you know of any accidents caused by steering failure?

Yes - 2 people a piopossist and analogy order avail emplaye alded"

In one case, a boater in a 6-month-old 18-foot runabout rammed into a bulkhead when a nut came loose on his steering system.

No serious damage occurred.

In the second case, a young boater hit a bridge after corrosion had limited the steering range. The boat would not steer fast enough to make a sharp turn and avoid collision.

Note: Four people mentioned that shift cables failed when the boat operator thought he was in forward, but actually was in reverse, or vice versa.

2. What improvements would you like to see made on steering mechanisms?

Sixty percent said they would like to see improvements in the following order of priority.

- a. Corrosion-proof fittings
- b. Better lubrication seals
- c. More lubrication fittings
- d. Better location for lubrication fittings (i.e., on end sleeves)
- e. Improved, non-hardening lubricant
- f. Stronger, better-designed motor connections and ball joints for larger tandom mounts.

4. Do you have any problems installing systems?

Yes - 75%

Problems listed in order or prevalence are:

- a. Inadequate part substitutions by manufacturer often cables are too long or too light.
- b. Non-standard nature of many steering systems often forces mechanic to search for hard-to-find parts and thus he will use a less than ideal substitute part. This causes hard steering and excessive cable wear.
- c. If one part is bad, but cannot be located, it is sometimes necessary to change most of the system at great relative expense in order to get the system functioning properly. Customers tend to put pressure on dealers/mechanics to make repairs the cheapest way possible, and mechanics often worry about what the consequences may be.

A number of mechanics noted that steering units last, on the average, only two or three years under normal use. Few people are concerned with maintaining them or even giving the unit annual lubrication. Six interviewees admitted that they replace steering units in part or whole for a number of wealthier customers as a normal part of yearly service.

It appears that in Miami the attitude of boaters is to generally ignore steering mechanisms until they fail, and then replace them. Failures rarely result in accidents of any consequence, so boaters don't seem to worry about it. Most failures appear to happen directly after periods of disuse. The potential failure is usually discovered by an owner or mechanic before placing the boat in the water and it is repaired then.

IV. TYPE I FAILURES

Two complete failures are documented. Both are mechanical systems in which the steering cables had to be replaced since rust and corrosion made it impossible to steer the boat. Corrosion and rust seem to be greatest where the cable forms the steering arm at the stern of the boat. This is the area where exposure to water and weather are greatest. Another factor which contributes to deterioration of the cable at this point in outboard motor boats is the removal of the motor from the water when the boat is not in use. In some instances, tilting the motor up puts an undue strain on the steering cable causing the outer covering to tear or pull loose, consequently subjecting the inner cable to the elements. However, design modifications make it less likely that some of the newer systems will bind up in this manner.

All mechanics surveyed indicated that rust or corrosion was the principal cause of steering failure. There was also unanimous agreement that such failures could be substantially reduced by regular lubrication of the system, i.e., at least at the beginning and end of the boating season. Periodic visual inspection of the system was also recommended by eight mechanics. Freeze-ups of the steering due to rust or corrosion are common after long periods of storage. For example, most steering failures of this type occur in the early spring after the boat has been stored for the winter. Failures due to rust or corrosion rarely lead to accidents because the owner must have the condition corrected before the boat can be used.

V. TYPE II FAILURES

One partial failure is documented in this survey. A defective system does not accompany this documentation because only a minor adjustment to the system was required to correct the condition.

VI. TYPE III FAILURES

No Type III failures are documented.

VII. FAILURES THAT RESULTED IN ACCIDENTS OR NEAR ACCIDENTS

No documented incident of a steering failure that caused an accident or near accident is included in this survey. Failures of mechanical systems that result in accidents are apparently extremely rare. One mechanic reported a case where the steering cable broke nearly causing an accident. Two mechanics reported incidents where quick couplers on steering arms failed and minor accidents resulted. One mechanic reported that he knew of several instances in the past 25 years where cables on tiller/cable systems snapped causing the boat to veer sharply to one side or even capsize. One such accident in Georgia involved a fatality. The other mechanics interviewed did not know of any accidents or near accidents caused by steering failure and it was their opinion that operator error, not mechanical failure, was the greatest single factor in boating accidents.

VIII. OTHER TYPES OF STEERING FAILURE OR PARTIAL FAILURE

The survey indicated five other types of failure or partial failure. These are listed below.

- 1. In an effort to free a "frozen system" the operator turns the steering wheel with sufficient force to break the gears in the helm assembly or snap the steering cable.
- "Hard steering" resulting from rust or corrosion of the steering cable. This condition can be corrected by lubrication of the unit; however, if left unattended, the result is usually total system failure.
- 3. Improper installation of the steering system by boat manufacturer can result in steering failure. The result is a less responsive system; total steering system failure can occur if the cable binds under these conditions.
- 4. Tiller/cable systems are more prone to failure than mechanical systems because they are more complex. For example, tension of the steering cables must frequently be adjusted. If the cables are too tight, the pulleys give way. Conversely, if there is insufficient tension, the cables step off the pulleys causing the steering to bind and sometimes snap the cable. Further, the entire system is more exposed, thus increasing the likelihood of rust or corrosion.
- 5. Partial steering failure can be the result of improperly adjusted trim tabs.

IX. MECHANICS' RECOMMENDATIONS

The mechanics interviewed made the following recommendations:

- 1. Periodic lubrication of the steering systems will substantially reduce rust and corrosion and the probability of steering failures. Systems should be lubricated according to use and conditions, but always at the beginning and the end of the boating season.
- 2. Components exposed to salt water or weather should be made of brass or stainless steel whenever possible.
- 3. When not made of corrosion-proof metal, the exposed parts of the mechanism should be covered with grease or rinsed with clear water.
- Cables should be kept away from the exhaust manifold since heat speeds deterioration.
- The system should be inspected visually each time the boat is used.
- 6. Steering system parts should be standardized within the boating industry. This would eliminate poor substitutions.

- 7. Manufacturers should improve quality control on factoryinstalled systems. A large number of systems are poorly installed, and often with wrong-part substitutions.
- 8. Trim tab adjustment can greatly affect the way a boat steers. Adjustment is often overlooked or avoided as it can be time consuming and is usually made by trial and error. A better trim tab adjustment methodology should be developed.
- 9. Improved lubrication seals could be an important way of increasing required service intervals.
- 10. Lubricants often harden due to salt and dirt buildup. There appears to be an actual chemical change in most grease after a period of disuse. The material becomes so hard that it can freeze up a system which is not otherwise very corroded. Perhaps improved silicone lubricants could be tested to see if they harden.

b. Steering exeten parts wheal he erraduced edible the

APPENDIX D

OUTBOARD MOTOR REMOTE STEERING SYSTEMS ABYC PROJECT P-17

LIST OF ILLUSTRATIONS

Figure		Page
1	Motor Mounted Steering	D-6
2	Steering Output Ram	D-7
3	Boat Mounted Steering	D-8
4	Steering Shafts and Steering Wheel Hubs	D-9
5	Wheel Description	D-10
6	Steering Wheel Impact Test Fixture	D-10

OUTBOARD MOTOR REMOTE STEERING SYSTEMS

PROJECT P-17 (PROPOSED OCTOBER 21, 1974)

ABYC P-17-74

Based on ABYC's assessment of the state of existing technology and the porblems associated with achieving the requirements of this standard, ABYC recommends compliance with this standard by August 1, 1977.

P-17.1. PURPOSE

These standards and recommended practices, establish minimum strength requirements of remote steering systems and the major component items thereof, and are to facilitate safe connection of boat steering systems to outboard motors.

P-17.2. SCOPE

These standards and recommended practices apply to remote steering systems used with single outboard motor installations of 20 horsepower to and including 150 horsepower. These standards and recommended practices do not apply to cable over independently mounted pulley steering systems.

P-17.3. DEFINITIONS

- a. Steering System An assembly including all components necessary to transmit remote manual effort to and including the steering output ram.
- b. Minimum Steering Ability Steering capability after test such that the steering system must turn the outboard motor, under static conditions, through an arc of at least 5 degrees each side of the mid-position with no more than 20 foot-pounds of torque at the helm exerted through the wheel or other normal control. These limits are not meant to define a condition under which a boat can or cannot be safely operated, but are intended to provide quantitative limits for design and testing purposes.
- c. Total Steering Loss Complete loss of the ability to steer the boat from the helm position by application of manual effort to the wheel or other helm control provided.

P-17.4. REQUIREMENTS - IN GENERAL

- a. This standard provides requirements for two steering systems with respect to the attachment at the output end:
 - (1) Motor mounted steering system.
 - (2) Boat mounted steering system.
- b. The steering system selected shall be installed in accordance with this standard.
- c. The interface between the outboard motor and the steering system shall be the attachment point at the output end as shown in Figure 2.
- d. Steering system threaded fasteners, the integrity of which is necessary to the maintenance of steering control, shall have a locking feature to prevent loosening which should be of a type that will preclude accidental omission during field installation or maintenance.

P-17.5. REQUIREMENTS - OUTBOARD MOTORS

a. The steering stops on the outboard motor shall permit at least 30 degrees of angular movement either side of center.

© 1974 American Bost and Yacht Council, Inc.

(P-17.5)

- Outboard motors where applicable shall incorporate the dimensional requirements indicated in Figure 1.
- c. The outboard motor shall include the necessary fittings to attach to the steering output ram as shown in Figure 2.
- d. The outboard motor shall be designed so there shall be no damaging interference between the motor, its accessories, and both the boat mounted system installed as shown in Figure 3 and the motor mounted system, provided the motor is designed for both systems. Appropriate written information and installation instructions shall be provided, clearly indicating the type of steering system(s) that should be used. Motors may be designed for special steering systems providing the non-standard components are provided with the motor along with the necessary installation information.
- e. Outboard motors shall be designed with geometry to insure that a static load of 750 pounds, applied at the steerer connection point normal to the steering arm in its normal place of operation, throughout the maximum steering arc, will not result in steering output ram loadings greater than those specified in ABYC P-17.8.b.(1).

P-17.6. REQUIREMENTS - STEERING SYSTEM

- a. Motor mounted steering systems shall incorporate the dimensional requirements indicated in Figure 2.
- b. Boat mounted steering systems shall incorporate the dimensional requirements indicated in Figures 2 and 3.
- c. Quick-disconnect fittings relying upon spring force for connection integrity shall not be used.
- d. Steering cables shall be marked with a steering system length which shall be the length from the center of the steering wheel shaft to the end of the steering output ram at the mid-travel position.
- e. Steering helm manufacturers shall indicate the maximum diameter and deepest dish wheel, (See Figure 5) which may be used with the helm, in appropriate written information, including installation instructions. In addition, this information shall be permanently marked on the helm assembly so as to be visible when the helm is installed with the wheel removed.

P-17.7. REQUIREMENTS - INSTALLATION

- a. Steering System installers shall select either the Motor Mounted Steering System or the Boat Mounted Steering System unless the installation is specifically intended for outboard motors having special requirements.
- b. When installing Motor Mounted Steering Systems in outboard boats, steering cables shall be selected which, as installed, at mid-travel position, will reach at least 10 ½ inches beyond the motor centerline.
- c. When installing Boat Mounted Steering Systems in outboard boats, steering cables shall be selected which, as installed, at mid-travel position, will reach at least to the motor centerline. The cable shall be attached to the boat so as to position the cable anchor swivel with respect to the transom motor centerline as specified in Figure 3.
- d. Steering cable bend radii and total degrees of bend, as installed, shall comply with cable manufacturer's recommendation.

the sale of the sale each stack of the sale of the

(P-17.7.)

e. Steering System installers shall select matching steering wheels and helm shafts. Current fit configurations are shown in Figure 4.

P-17.8. REQUIREMENTS - TESTING

- a. As Installed Tests These tests are intended to establish the acceptability of the strength of steering systems, as installed, in a boat to the interface with the outboard motor as defined in ABYC P-17.4.c.
 - (1) Steering systems shall withstand static loads in either direction of 750 pounds applied at the connection hole of the steering output ram along the axis of the steering output ram without deformation that, following this test, will cause any loss in steering capability or cause dimensional change that will result in non-compliance with Figure 3. The permanent deformation shall not exceed .25 inches measured along the axis of the output ram.
 - (2) Steering systems shall withstand tangential loads in either direction of 100 pounds applied at any point on the steering wheel rim, and separate axial loads of 150 pounds in either direction, distributed over 4 inches of rim at any location maintaining minimum steering ability.
- Component Tests These tests are intended to establish acceptable minimum design criteria for components of steering systems.
 - (1) Steering output and cable assemblies (including boat mounted system hardware) and their integral fittings shall withstand a load of 2000 pounds in tension and compression, applied at the connection hole of the steering output ram, throughout the travel range without severance of components. A separate cantilever load of 200 pounds shall be applied at the centerline of the hole in the steering output ram with at least 7 ½ inches of the ram unsupported without more than .05 inches of permanent deflection at the ram hole.
 - (2) Steering output assemblies of steering systems not using push-pull cables, or cable over independently mounted pulley systems, shall withstand the same loadings specified in ABYC P-17.8.b.(1).
 - (3) Helm assemblies shall incur no loss of operating function after the following tests when equipped with the largest diameter and deepest dish steering wheel for which the helm is rated.
 - (a) Axial Load Test A 150 lbs. push-pull load shall be applied for 10 cycles at a duration of 5 seconds per loading, applied at any location on the rim of the wheel in a direction parallel to the axis of the steering shaft.
 - (b) Tangential Load Test A 100 lbs. push-pull load shall be applied tangentially in the plane of the steering wheel for 10 cycles at a duration of 5 seconds per loading, applied at any location on the rim of the wheel at any point in its total steering range.
 - (4) Steering wheels shall be subjected to 3 cycles of thermal conditioning before mechanical tests are performed. 1 cycle of thermal conditioning is defined as:
 - 3 hours at 70° ± 3°F (21° ± 2°C)
 - 3 hours at -300 ± 30F (-340 ± 20C)
 - 3 hours at 700 ± 30F (210 ± 20C)
 - 3 hours at $160^{\circ} \pm 3^{\circ}F$ ($71^{\circ} \pm 2^{\circ}C$)

At the conclusion of the thermal cycling, parts shall exhibit no visible degradation of structural components, except for minor cracking of plastic.

At a temperature of 68°-75°F (20°-24°C), for at least 3 hours, the wheels shall then in sequence withstand the following mechanical tests.

- (a) Axial Test A 150 lbs. push-pull load, distributed over 4 inches of the rim at any location shall be applied for 10 cycles at a duration of 5 seconds per loading without fracture or permanent deformation in excess of 1 inch at the rim.
- (b) Tangential Load Test A 100 lbs. push-pull load at any location on the rim shall be applied tangentially in the plane of the steering wheel for 10 cycles at a duration of 5 seconds per loading without fracture.
- (c) Impact Load Test No. 1 Wheels shall withstand a single impact of 120 foot lbs. at any location on the rim without propagation of any cracks induced by thermal cycling, appearance of new cracks or deformation that would cause loss of minimum steering ability when installed on a steering system. [See ABYC P-17.8.b.(5) and Figure 6 for impact test fixture. (h = 8.25 inches)]
- (d) Impact Load Test No. 2 Wheels shall withstand a single impact of 200 foot lbs. at any location on the rim without sustaining total steering loss when installed on a steering system. [See ABYC P-17.8.b.(5) and Figure 6 for impact test fixture. (h = 13.75 inches)]
- (5) The impact test fixture shall comprise a leather bag of 10" diameter completely filled with 175 pounds of lead shot suspended on a free swinging cable such that the center of mass shall be 90 ± 6 inches below the supporting pivot. The impact face of the bag shall be a 10 inch diameter end. The bag shall be elevated through sufficient arc to impart the desired value of impact upon a rigidly mounted steering wheel by swinging the bag as indicated in Figure 6. Other devices than that specified, such as a falling weight bag, may be used providing equivalency can be verified.
- c. Corrosion Testing This test is intended to establish acceptable minimum corrosion resistance for steering systems. Tests shall be conducted on 5 feet of the output end of an assembled steering system under cyclic test conditions. Assemblies shall be lubricated according to steering system manufacturer's specifications and installation instructions, but no additional lubrication may be used after commencement of testing.


(1) Test Procedure -

- (a) Exposed elastomer sheathing and seals shall be subjected to radiation with an intensity of 60 75 microwatt per square centimeter at 340 nanometer wave length for 200 hours prior to corrosion testing.
 - (b) The cable assembly with the output end shall be placed in the test chamber in a horizontal position with all covers or protective sleeves in place.
 - (c) The environmental test shall be conducted and prepared for evaluation in accordance with ASTM B117-73 (ANSI Z118.1) Standard Method of Salt Spray (Fog) Testing.
 - (d) The length of the test shall be a minimum of 200 hours.


[P-17.8.c.(1)]

- (e) The cyclic sequence for operation of the steering system during salt spray testing shall be 4 hours of 4 to 6 cycles per minute of at least 6 inches of cable travel during every 24 hour period under a minimum compression load of 50 lbs.
- (f) At the conclusion of the 200 hour exposure period, the individual components shall be examined for evidence of corrosion, binding or other functional problems.
- (2) Evaluation of Test Results Corrosion failure is defined as the appearance of pitting, scaling or surface buildup visible to the unaided eye at the normal reading distance on internal or external surfaces that have relative motion during operation or installation. Components shall perform their functions as originally designed.


© 1974 American Boat and Yacht Council, Inc.




© 1975 American Boat and Yacht Council, Inc.




© 1975 American Boat and Yacht Council, Inc.




© 1975 American Boat and Yacht Council, Inc.



© 1975 American Boat and Yacht Council, Inc.





SPLINE DATA- SHAFT:		
DIAMETRAL PITCH	-	29-56
NO. OF PITCH	-	19
PRESSURE ANGLE	-	45*
OUTSIDE DIA.	-	700-687
MINOR DIA.	-	.6207-6167
PITCH DIA.		5552
TOOTH THICKNESS @ RE		.05800565
BASE CIRCLE DIA		4633

SPLINE DATA-MUBI		
DIAMETRAL PITCH	-	29-58
NO. OF TEETH	-	19
PRESSURE ANGLE	-	45°
OUTSIDE DIA.	-	703-701
MINOR DIA.	-	636-630
PITCH DIA.	-	4552
TOOTH THICKNESS OPD		0640-0652
BASE CIRCLE DIA.		A633

STEERING SHAFT AND WHEEL FIT ST'D-SPLINE

FIGURE 5 - WHEEL DESCRIPTION




FIGURE 6 - STEERING WHEEL IMPACT TEST FIXTURE

 $D = 90 \pm 6$ (inches) W = 175 (pounds).

= $D \cos \phi$ (feet) = $D - D \cos \phi$ (feet) = Impact Value (foot pounds) $= W(h) = W(D-D\cos\phi)$ $h = \underline{I} = \underline{I}$ W 175 Foot Lbs. Inches 120 8.25 200 13.75 90± 5°

© 1975 American Boat and Yacht Council, Inc.

APPENDIX E

RECREATIONAL BOAT
STEERING SYSTEM TESTING

M. L. Vande Steeg

Prepared for
U. S. COAST GUARD
Contract DOT-CG-81-74-1098

OUTBOARD MARINE CORPORATION
Marine Engineering - Engine Section

August 1974

The state of the s

ABSTRACT

This project was initiated in response to a Coast Guard Procurement Request #81-0713-74. Current OMC push-pull steering systems were tested both dynamically and statically. Steering loads under actual operating conditions were measured using the following boat-engine configurations:

- 1. 19-foot Evinrude boat equipped with dual 135 hp outboards
- 2. 19-foot Evinrude boat equipped with a single 225 hp inboard/outboard
- 3. 24-foot Wellcraft boat equipped with dual 165 hp inboard/outboards

Static loads were applied to the following steering systems:

- 1. thru-tilt single 50 hp
- 2. thru-tilt single V-4
- 3. transom mounted single V-4
- 4. thru-tilt dual 50 hp
- 5. thru-tilt dual V-4

Critical deflections were recorded along with the level of loading that caused system failure.

Constant Section Constant

CONTENTS

	ract .																									ii
	of Ill				•				•						•											iv
List	of Tab	les .	• • •	٠	•	•		•	•	•	•	•	٠	•	٠	•	٠	•	•	٠			٠	•	٠	V
ı.	INTRO	DUCTIO	N	٠	•	•	•	•	•		•	٠	•	٠	٠	٠			٠	•		•				1
II.	DYNAM	IC TES	т РНА	SE	•	•	•	•	•		•	•		200	ė	•	•	•		ŕ	•	•	•			2
	Α.	Equip	ment	•	•	•	•	•	•		•	•	٠	•	٠	•	100	•			•	i	•	•	•	2
	В.	Resul																								
	c.	Discu																								
III.		C TEST																								
	A.	Equip																								
	В.	Result																								
		2.	Sing:																							
		3.	Dual																							
		4.	Sing																							
		5.	Dual																							
		6.	Dual	Er	ıgi	ne	S	ing	gle	e C	ab	le	•				•			•						27
		7.	Stati	Ĺc	Vs	. :	Sir	nu:	lat	ed	I	mpa	act	: 1	٥٥:	ıds										28
	c.	Discus	ssion		•		•				•	•	•	•	•						•					31
IV.	SUMMA	RY .		•	•						•	•		•	•	•	•		•	•		٠	•	•	٠	32
APPEN	DIX A	- Dynar	nic Te	est	D	ata	a .							•			•		•	•		•				34
APPEN	DIX B	- Stati	lc Tes	t	Da	ta							•					•				•				53
APPEN	DIX C	- Stee	ring S	èvs	te	m 1	Los	ad	An	al	VS	is					19					15				70

LIST OF ILLUSTRATIONS

Figure		P	age
1	Dual 135 hp Outboard		3
2	Steering Arm Load Cell	•	4
3	Stern Drive Steering Bracket Load Cell		5
4	Stern Drive Steering Bracket		6
5	Peak Dynamic Loads		11
6	V4 Swivel Brackets with Loading Arms	•	14
7	Steering Assembly	•	21
8	Steering Load Vs. Ram Deflection		22
9	Simulated Impact Steering Loads - Compression	•	29
10	Simulated Impact Steering Loads - Tension		30

ACTIONES C - Reporting System Sound Maddischer Commission Commission Statement

LIST OF TABLES

Table	<u>Pa</u>	ge
1	Dynamic Test Data	9
2	Dual 50 hp Steering Load Distribution	8
3	Cable Extension/Compression	3
4	Ram Bending	3
5	Dual V4 Steering Load Distribution	6

I. INTRODUCTION

The project on which this report is based had a dual purpose. It included making dynamic measurements of the loads induced in recreational boat steering systems and testing certain steering systems under static loads to determine the level of loading that would cause impairment or failure of the system.

The dynamic tests were designed to measure the steering loads under the most severe conditions. Driver safety was a factor in determining the types and severity of maneuvers performed with each boat; however, in general they included wave-jumping with high-speed prop re-entry and high-speed turns including total spin-outs. All of the test runs would be considered abusive-type driving. In addition, the 135 hp outboards were operated with a misadjusted trim geometry.

The static tests were structured so as to define the steering system geometry that would place a maximum load on the member of the system that will fail initially under increasing loads. Critical deflections were measured under various loads to determine the level of loading that causes the onset of permanent deflection and that which causes failure of the system to function throughout its normal range. Whenever possible, the systems were misadjusted to ascertain the worst possible condition.

II. DYNAMIC TEST PHASE

A. Equipment

The following boat-engine configurations were tested:

- 1. 19-foot Evinrude equipped with dual 135 hp outboards
- 2. 19-foot Evinrude boat equipped with a single 225 hp inboard/outboard
- 3. 24-foot Wellcraft boat equipped with dual 165 hp inboard/outboards

The dual outboard installation was rigged with dual push-pull steering cables and a tie-bar. Figure 1 is a photograph showing the dual thru-tilt steering system that was used. The steering loads were measured using a strain gage bending bridge mounted on machined sections of the steering arms, as shown in Figure 2. This arrangement allowed steering torque to be determined directly from the load cells.

The dual inboard/outboard installation was rigged with a single push-pull cable and a tie-bar. The steering bracket that mounts on the outdrive was replaced with one that was designed to accommodate a strain gage bending bridge. This load cell is shown schematically in Figure 3. It was designed in such a manner that the steering load would be measured as a torque about the outdrive swivel axis.

The single inboard/outboard was equipped with an external push-pull steering system. The same load cell that was used for the dual installation was mounted on the outdrive. Figure 4 is a photograph of the bracket. Again, the steering load was measured as a torque about the outdrive swivel axis.






FIGURE 1. Dual 135 hp Outboards.

STEERING ARM LOAD CELL



STERN DRIVE STEERING BRACKET LOAD CELL






FIGURE 3




FIGURE 4. STERN DRIVE STEERING BRACKET.

II. DYNAMIC TEST PHASE

A. Equipment (continued)

A portable power supply that operates from a 12-volt auto battery was used to power the strain gage bridges and Dana amplifiers that condition the bridge signals.

A magnetic pick-up that sensed the armature magnets in the flywheel was used to provide engine rpm data for the outboard engines. On the inboard engines, an attenuated signal from the ignition coil was used to provide the engine speed data.

On all of the boats, a rotary potentiometer was coupled to the steering wheel shaft. It was wired into a bridge-type circuit powered by a 9-volt battery and used to record the steering wheel position.

A pitot tube and gauge provided the operator with boat speed information.

A portable Lockheed magnetic tape recorder was used to record all of the data. In addition, a headset was utilized to allow the driver to record on the voice track any information that he felt was pertinent to the testing.

II. DYNAMIC TEST PHASE (continued)

B. Results

The dynamic test data was recorded on magnetic tape and later played back into a Visicorder. Appendix A contains a number of sample Visicorder traces, along with pertinent calibration information. Table 1 lists the maximum load for each boat and the conditions under which the loading occurred.

The steering loads are indicated as being in foot-pounds of torque. This is the torque caused by the engine or outdrive about its swivel axis.

Indicating the load in this manner eliminates the need for relating a force to its moment arm and to the angle that it forms with a line normal to the steering arm or bracket. Due to the tie-bar and single steering cable, the torque of the dual inboard/outboard installation was automatically summed at the load cell. The torques produced by dual outboards were recorded individually and then summed electronically during playback.

The dual outboards were initially tested in a normal tilt position. The engines were then tilted out past the normal operating range. As shown in Table 1, the maximum steering load increased from 505 foot-pounds to 600 foot-pounds. When an outboard engine is tilted out past the optimum tilt position, the boat tends to "porpoise," which accentuates the wave-jumping action. If the boat is turned at the same time as it is porpoising, the steering loads are very high.

DYNAMIC TEST DATA

BOAT	ENGINE	AMBIENT			TYPE OF	MAXIMUM	BOAT	ENGINE	STEERING	TILT
	HP	WIND MPH	TEMP.	WATER*	DRIVING	LOAD FT-LBS	SPEED MPH	RPM	POSITION	ANGLE
19'	DUAL 135	0-5	40	MODERATE	WAVE JUMPING	505	42	5000	0°	-2°
19'	DUAL 135s	0-5	40	MODERATE	WAVE JUMPING 600		45	5400	10° STBD	9°
19'	I/0 225	10	30	MODERATE TO LIGHT	HARD TURN	285	45	5400	22° STBD	0°
241	DUAL 165 1/0	0-10	36	MODERATE TO HEAVY	WAVE JUMPING	360	45**	4800	0°	-3°

^{*} moderate water condition indicating 2 to 3-foot swells

^{**} estimated


II. DYNAMIC TEST PHASE

B. Results (continued)

The 24-foot Wellcraft was tested in relatively rough water. The boat could readily be jumped out of the water; however, the boat did not lend itself to hard turns of any type. The driver's seat was elevated and had little side support. Also, a fuel tank and motor mount were torn from their supports during the testing. Adding any side impacts to the testing maneuvers would undoubtedly have caused additional damage to the boat. The maximum load on the steering system was 360 foot-pounds of torque. The maximum load on the single inboard/outboard steering system, 285 foot-pounds, occurred during a high speed turn. The boat nosed down while entering the turn, causing the rear of the boat to raise up and spin around. As the rear of the boat dropped back into the water, it caused a high side impact on both the boat and outdrive.

The maximum loads on the steering systems are of relatively short duration. Figure 5 shows the peak loads on the same time axis to illustrate the impact nature of the loads. The short duration of the peak loads, combined with the friction and mechanical advantage of the system, causes little (if any) of the load to be felt at the steering wheel.





II. DYNAMIC TEST PHASE (continued)

C. Discussion

In order to determine the loads on individual members of the steering system, the geometry of the system must be known. For this reason, the steering angle was recorded along with the load cell data. The maximum load of 600 foot-pounds on the dual outboard steering system occurred when the engines were turned at a 10° angle. All of the peak loads greater than 300 foot-pounds occurred at angles of 16° or less. The 16° of engine angle represented one full turn of the steering wheel which, when applied at full speed, would put the boat into a relatively hard turn. The significance of the angle at which the peak loads occurred is explained in greater detail in the STATIC TEST section.

The 360 foot-pound load on the dual 165 hp inboard/outboard steering system occurred at 0° steering angle. The maximum load of 285 foot-pounds on the single inboard/outboard occurred at a 22° steering angle. The dual 165 hp inboard/outboard installation did show a decrease in maximum loading as the engine angle increased. However, the peak loads on the single 225 hp inboard/outboard installation were relatively uniform throughout the entire steering range. The steering angle is less critical with the external push-pull steering system, since there is no bending moment on the ram and a change in angle will only change the axial load on the cable for a given engine steering torque.

of a seminar focus as doctor selected

A. Equipment

All of the static steering systems testing utilized a 19-foot Evinrude boat. The steering systems were installed in a normal manner, except that the steering wheel was replaced with a steel bar to facilitate locking the system at various engine angles.

The stern and swivel bracket assemblies, with the engines removed, were used in the static testing. Steel bars were bolted to the steering arms to apply the torque, which normally is transmitted through the engine.

Figure 6 is a photograph of the dual V4 thru-tilt steering system with the arms used to load the system attached.

The torque input to the steering system was measured using a Dillon spring scale in line with the loading force. An axial load bridge was placed on the tie-bar to allow measurement of the load transmitted through the tie-bar on the dual installations.

B. Results

1. Single V4 Transom Mounted

The swivel bracket was placed in the 2° tilt position and loaded at various angles and all four elevations. Appendix B contains a complete listing of all of the data. Using a load of 560 ft-lbs, the only measurable deflection occurred in the push-pull cable. Depending upon the load direction, it would elongate or compress approximately .5 inch. There were no permanent deflections at this level of loading.




FIGURE 6. V4 SWIVEL BRACKETS WITH LOADING ARMS.

B. Results

1. Single V4 Transom Mounted (continued)

To define the failure point, the ram was placed in its most vulnerable position. The engine was turned to a 32° angle, and the stern bracket was moved to the uppermost elevation. The torque was applied in a clockwise direction, which placed the steering ram in compression. The load was increased to 890 ft-lbs. At that point, the ram buckled, rendering the steering system inoperable. In addition, the transom bracket that supports the swivel ball had begun to separate under load.

2. Single 50 hp Thru-Tilt

The steering arm deflections were measured by attaching a pointer to the arm at the engine pivot point and directing it to a scribed point midway between the drag link and tie-bar attachment points. The steering arm deflection for all loads up to 620 ft-lbs was less than .06 inch.

The extended length of the ram measured both loaded and unloaded would be indicative of any compression or elongation of the cable. The cable compressed and elongated approximately .5 inch while under load.

The most critical loading in the system is the bending moment on the ram. According to an analysis of the 50 hp thru-tilt system, as outlined in Appendix C, the ram will have a maximum bending moment for a given torque when the engine angle is at 15°. The following fore-aft deflections of the ram were recorded:

B. Results

2. Single 50 hp Thru-Tilt (continued)

LOAD ft-1bs	DEFLECTIONS UNDER LOAD inches	PERMANENT DEFLECTIONS inches	
388	.75	.12	
484	.75	.12	
542	1.00	.19	

The .12 and .19 inch permanent deflections caused a drag on the steering system. However, it was still operable throughout its entire range of travel. The ram appeared to be strain-hardening at this point. Therefore, it was replaced with a new ram and cable assembly. The engine angle was selected so that under loaded conditions, it would be at approximately 15°. The system was loaded to 620 ft-lbs. The ram deflected 1.5 inches under load with .62 inch permanent deflection. A permanent deflection of the ram of .38 inch or greater was considered a failure of the system since it could not be readily operated throughout its full range of travel. The amount of permanent deflection of the ram that a system can tolerate and remain operable may vary from engine to engine dependent upon the condition of the tilt-tube. A worn tilt-tube with rounded edges would be more tolerant of a bent ram than a new tilt-tube with less clearance.

deemed graderic control a byte John boy will be builted a mention of the action

- B. Results (continued)
 - 3. Dual 50 hp Thru-Tilt

The dual engine dual cable system with the tie-bar is a statically and mathematically indeterminate system. If the fraction of the total load that each cable is bearing can be determined, the cable, ram, and drag link can be expected to respond as if they were a single engine carrying that particular load. The axial load cell on the tie-bar provided the lateral force acting on each steering arm. This force could be resolved into an axial force and a normal force for any steering angle. Knowing the normal force and the torque input into the system, the load on each assembly could be calculated. Table 2 illustrates the load distribution of the dual 50 hp installation.


The maximum load that either cable supports is 66% in either tension or compression. Using the information gained from the single 50 hp testing, this would indicate that the total loading on the system would have to exceed 500 ft-lbs before any permanent deflection of the ram would occur. This is indeed the case, as it took 775 ft-lbs to permanently deflect a ram .12 inch. Another factor that became apparent during this test series is the fact that as the total load is increased, it becomes more evenly shared between the cables. This tends to increase the load necessary for both the initial yielding and the point of failure. Obviously,

DUAL 50 HP STEERING LOAD DISTRIBUTION

ENGINE LOADED	ENGINE ANGLE	LOAD FT-LBS	LOAD DIRECTION	% OF TOTAL LOAD 18' CABLE 20' CABLE	
44-					
STBD	0°	484	+	48	52
STBD	0°	484	stoled - site ha	66	34
PORT	0°	484	*	60	40
PORT	0°	484	-	46	54
STBD	25°	484	+	66	34
STBD	25°	484	este "E roya	and 51 at any	49
PORT	25°	484		36	64
PORT	25°	484	-	58	42
STBD	-25°	484	+	60	40
STBD	-25°	484	-	36	64
PORT	-25°	484	almay ‡mizis	51	49
PORT	-25°	484	ula gr⊒bu .o	64 100	36 m J

*LOAD DIRECTION

3067 30



The second of the second secon

B. Results

3. Dual 50 hp Thru-Tilt (continued)

the point of failure is greater than 775 ft-lbs, and the information gained from the single 50 hp combined with the load-sharing data would indicate that the load necessary to fail the dual cable system is in excess of 1000 ft-lbs.

analytically that the maximum bending moment on the ram occurs at 17° for the single 50 hp under a given steering load. The steering angle at which the dual 50 hp data was recorded was 25°; however, the analysis showed that the difference in the bending moment between 17° and 25° was less than 3.5 percent. Since in a dual system the ram in tension receives a greater share of the load as the steering angle increases, the critical angle for the dual 50 hp installation would in all probability be closer to the 25° steering angle.

4. Single V4 Thru-Tilt

The V4 thru-tilt steering system geometry is different than the 50 hp in that the tilt tube centerline is displaced away from the attachment point on the steering arm. Appendix C illustrates the differences in loading that this causes. The cable force loading varies substantially as the ram moves from full extension to full retraction.

Because of the increased drag link force component normal to the ram,

B. Results

4. Single V4 Thru-Tilt (continued)

the bending moment on the ram is increased. These effects can be seen in the data listed in Tables 3 and 4.

As Table 4 shows, the ram begins to deform plastically when loaded with 400 ft-lbs and exceeds the failure deflection of .38 inch when loaded at 500 ft-lbs. In order for this to occur, the engine must be at a 25° angle and the loading must be such that it places the cable in compression. The critical angle was derived from the analysis in Appendix C and verified with the static test data. The criteria that the load must place the cable in compression and not in tension is due to the system geometry, which is sketched in Figure 7. As shown, the force along the drag link can be resolved into two components at the pinned connection with the block. The force F_1 with moment arm d creates a couple at the end of the ram that forms part of the bending moment. Whenever this force acts in the -x direction, the bending will occur in the -y direction, decreasing d. If d passes through zero and is deflected to the other side of the centerline of the ram, the bending moment created by F1 will oppose the bending moment created by F2. Figure 8 illustrates this with a plot of the load versus the actual total (elastic and plastic) deflection of the end of the ram.





FIGURE 7

E-27



CABLE EXTENSION/COMPRESSION

ANGLE	LOAD FT-LBS	EXTENSION INCHES	COMPRESSION INCHES
-25°	460	.5	.6
0°	460	.4	.2
25°	500	.2	.2

TABLE 3

will made extending party on - continues an house and

RAM BENDING

LOAD FT-LBS	ANGLE	DEFLECTION LOADED PERMANENT	
460	- 25°	. 19	.06
460	0°	.56	.25
400	25°	.75	.12
500	27°	1.75	.62

TABLE 4

of the order of booting a care to the town to bound to impost the

- B. Results (continued)
 - 5. Dual V-4 thru-tilt

The dual installation dual cable with tie-bar system is again statically indeterminate. In the case of a dual V-4 installation, however, the load is not shared as evenly as in the dual 50 hp system. Table 5 lists the load distributions for various angles and loads. There are 5 apparent factors that affect the load distribution:

- a. Cable in tension or compression in all cases, the cable in tension carries the larger share of the load.
- b. Ram extended or retracted as noted previously, when the ram is retracted, a given engine torque will create a higher load on the cable than when the ram is extended. This causes an extended ram to carry a larger proportion of the load.
- c. Cable length the two-foot difference in cable length can be seen by comparing two values with reversed geometry. The 18-foot cable carries a greater load than the 20-foot cable under similar circumstances. There apparently is a difference in elasticity due to the difference in length.
- d. Amount of loading as the level of loading increases, the

- B. Results
 - 5. Dual V4 Thru-Tilt (continued)
 - e. Engine angle the geometry of the thru-tilt steering system is such that a given cable movement causes a greater change in steering angle when the ram is retracted than when the ram is extended. In a dual engine dual cable installation, the engines are locked together with a tie-bar so that a steering angle change is the same for both engines. When the engines are turned away from the straight-ahead position, this causes the cable-tie-bar system to be placed in tension. With a properly installed steering system, the dual cable installation can assume as much as 150 pounds tensile force in the tie-bar when turned to a maximum steering angle. With this tension preload, the cable in tension will assume an additional proportion of the steering load.

Table 5 shows that in one case, a cable assumed 92% of a 500 ft-1b load. The cable was in tension, the ram was extended, the cable was the shorter of the two, and the engines were turned at a 24° angle. In this case, the load was sufficient to cause .06 inch of permanent deflection. The system failed when the same ram assumed a .38-inch permanent offset due to a total load of 700 ft-1bs.

DUAL V4 STEERING
LOAD DISTRIBUTION

ENGINE	ENGINE	LOAD	LOAD	% OF TOTAL LOAD	
LOADED	ANGLE	FT-LBS	DIRECTION*	18' CABLE	20' CABLE
STBD	0°	500	+	72	28
STBD	0°	500		44	56
PORT	0°	500	ura aipligas i	69	31
PORT	0°	500	nit elepanis 100	44	56
STBD	24°	500	+	92	8
STBD	24°	500	33 J. B. (12.)	26	74
PORT	24°	500	lister , gide	91	9
PORT	24°	500	ni ai a osai	24	76
STBD	-26°	500	+	77	23
STBD	-26°	500	-	19	81
PORT	-26°	500	a acer t a l'in	74	26
PORT	-26°	500	-	16	84
PORT	-26°	550	-	18	82
PORT	-26°	600	lags r- dans.	19	81
PORT	-26°	650	-	21	79
PORT	-26°	700	_	22	78
STBD	28°	700	kir ilsilif zen ei	22	78

*LOAD DIRECTION



ABLE 5

B. Results

5. Dual V4 Thru-Tilt (continued)

Since the cable loads in a dual cable system become more disparate when the system is placed in tension, an attempt was made to determine if one cable could be made to carry the entire load. By placing 130 pounds of tension on the system in the straight-ahead position, the cable in tension was forced into carrying essentially 100 per cent of the load. It should be noted, however, that the system was installed in a manner contrary to the installation instructions and it required a concerted effort to place that amount of tension on the system.

Due to the number of factors involved in determining the load on a single ram in a dual engine installation, as an additional test the engines were locked at a realistic steering angle of 15° and loaded in the direction that they would be during actual operation. Under these circumstances, which were dynamically feasible, the load necessary to fail the system was in excess of 1,200 ft-lbs steering torque.

6. Dual Engine Single Cable

Dual engine installations were not tested using only one cable although requested by the task order and specification sheet. Owner's manuals supplied with the engines and installation instructions supplied with the steering systems include safety warnings which state that dual installations must utilize a twin cable system. In addition, it was

B. Results


6. Dual Engine Single Cable (continued)


determined that the ram was the critical member of the thru-tilt steering system and it will fail at a certain level of loading independent of whether the load is supplied by one engine or by two engines connected with a tie-bar.

7. Static Vs. Simulated Impact Loads

In order to relate the static and dynamic data produced in this project, an attempt was made to reproduce the wave shape of the peak loads that were measured dynamically by impacting the lever arms used to load the steering systems statically. A V4 single installation was used for this simulated impact testing. Figures 9 and 10 show the results at the critical angle in both tension and compression. There was virtually no difference between the simulated impact loading required to permanently deflect and fail the ram and the level of loading that would do this statically. The time duration of the simulated impact loads. Therefore, it would be conservative, however not unrealistic, to assume that the level of loading which will cause failure is similar for static and dynamic loading as recorded during actual testing.

enwit contribute at the contribution of the co





III. STATIC TESTING (continued)

C. Discussion

The transom-mounted steering system is attached to both the engine and the transom with ball joints. For this reason, the load on the steering ram will only be axial. It is capable of withstanding relatively high loads before it buckles under a compressive load.

In the thru-tilt steering system, the drag link places a bending load on the ram. The ram is therefore the most critical member in the steering system. During the static testing, the engines were turned to a certain angle and loaded so as to place the cable in compression. This was the most critical geometry of the thru-tilt system, and the minimum failure points were recorded in these positions. In actual dynamic loading, however, this configuration would be virtually impossible to obtain. Whenever the engine is turned so as to extend the ram, the load on the side of the gearcase will be on the side that will place the steering cable in tension. As noted in the static test results, this factor increases the load necessary to cause permanent deflection of enough magnitude to fail the system.

The same directional limitation applies to the dynamic loading of the dual thru-tilt steering system. If the engines are turned so as to extend one of the rams, the load will be in the direction that will place that ram in tension. Also, the peak loads obtained during the dynamic testing of dual outboards occurred at relatively low engine angles. The total load on a dual cable system is more evenly distributed at low engine angles than at the extremes.

IV. SUMMARY

During the dynamic test phase, the test boats were subjected to a variety of maneuvers intended to place maximum loads on the push-pull steering systems. In addition, the trim geometry of the dual V4 outboards was intentionally misadjusted. The peak loads, measured at the engine pivot point, were as follows:

Dual 135 outboards 600 ft-lbs at 10° steering angle

Dual 165 inboard/outboards 360 ft-lbs at 0° steering angle

Single 225 inboard/outboard 285 ft-lbs at 22° steering angle

The static test phase involved applying static loads to both transom-mounted and thru-tilt steering systems. The transom-mounted steering system became inoperable after a load of 890 ft-lbs was applied at the engine pivot point. The ram is the most critical member of the thru-tilt steering system and, for a given torque, will deflect to a greater extent when the cable is in compression than when it is in tension. The angle is also critical in that the maximum bending moment on the ram occurs at a 17° steering angle for the 50 hp and at a 25° steering angle for the V4 geometry. Under these conditions, the 50 hp and V4 rams become inoperable when loaded with 620 ft-lbs and 500 ft-lbs, respectively.

The dual engine, dual cable systems with the tie-bar pose a mathematically statically indeterminate problem. The amount of total load that a single cable in a dual cable system can carry is 66% for the 50 hp system. A single cable in a dual V4 system can carry as much as 92% if that ram is extended and loaded in tension. At lower angles, the load is more evenly distributed. Critical system configurations were defined in the static testing, along with the level of loading that would cause failure under those specific

IV. SUMMARY (continued)

conditions. The peak dynamic loads cannot be compared directly with the minimum failure loads of the static tests, since under boating conditions the maximum loads do not occur at the most critical geometry. Engine angle and direction of loading are critical to determining the point of failure of the system.

APPENDIX A


DYNAMIC TEST DATA


DYNAMIC TEST DATA

Figures A-1 through A-14 are copies of Visicorder traces taken from the dynamic data. They are intended to show the variety of maneuvers and types of loading that occurred.

Figure A-15 is a calibration curve for the 135 hp outboard engine steering arm load cell. In a dual engine dual cable arrangement, the force applied by the drag link and that applied by the tie-bar do not coincide. This means that a given torque counteracted only by the tie-bar causes a different bending moment at the location of the bending bridge than the same torque counteracted only by the drag link. The calibration curves for the torque supported by the drag link only and by the tie-bar only are shown in Figure A-15 as lines A and C, respectively. Since the static testing showed that the strain indications were generally very close to the median line B, that curve was used to reduce the dynamic data. The maximum error introduced by using this line would be ± 10 per cent and would occur only if the total load were supported by a single cable.

The calibration curve for the stern drive steering bracket is shown in Figure A-16. The tie-bar axial load calibration curve is shown in Figure A-17.





AD-A035 574


COAST GUARD RESEARCH JNE DEVELOPMENT CENTER GROTON CONN F/6 13/10 INVESTIGATION OF RECREATIONA. BOAT STEERING AND CONTROL SYSTEMS--ETC(U) APR 76 JR TAYLOR COR/DC-8/76


UNCLASSIFIED


COAST GUARD RESEARCH JNE DEVELOPMENT CENTER GROTON CONN F/6 13/10 APR 76 JR TAYLOR USCG-D-119-76

NL


END
DATE FILMED
3:-77









E-46
































BEST_AVAILABLE_COPY

													1			
													and the same of			
													V			個人を対け
		(A) (A)							5) 10 10		977	0.0				
0		189 181 140	(M)			A.	PPEN	DIX	В	Clar No.		A CONTRACTOR		20 *		
	08		192 198 12	e e	s	TAT	IC T	EST	DAT	Α			800			
										a Di						
7	and a second	0		0		i co		•	1 (1) 1 (1)				61		00000	64 31 32
	0		(s) (s)	. 667					Ç,	37	01			ø		
				100										0881 550		0
ageles					-	A colorest	Train a	130						100	をから	ther.
				1880												
				17							Dr. oan			60	The same	Till

STATIC TESTING STREAMS STATES

SHEET #1

H	EL EVAPTOR	LOAD	9	*	-			3		60	31887		REGARDS
		77-136	34	INTTAL	LOADED	UNICOADED	INITIAL	LOADED	UNICADED	BXT.	Jom!		
2.	121	260	1780	0	3°	0	7.06	7.48	7.06	24:		15%	KET IN DIGATES
		1		J-	-3.5	./-	7.06	6.38	6.56		89.	+	RAM HORIZONTAL
				-91-	-18	-15°	4.00	3.50	4.001		.50	+	
				-16°	-13	-16°	21%	4.75	21.4	27	7	1	
				-26.	-23	-52-	2.31	2.88	2.62	70.		•	.31 EST
				-26-	-62-	-52-	2.25	1.75	2.25		.50	+	
				,51	.01.	.51	8.62	8.12	27.8		.50	+	
				.7/	20°	.91	8.88	9.25	88.88	.37		1	
				26°	30%	26°	10.32	10.88	10.32	.56		•	
				042	20°	042	2/10/	29.6	21.01		.50	+	
20	ब्ग 2	560	1780	.42	200	240	10.12	9.62	21:01		.50	+	
		1		25°	30.5°	26°	10.32	10.88	10.38	.56		1	.06 EXT
				091.	.02	.091	8.88	9.38	8.88	.50			
				15°	110	15.	8.75	8.19	8.69		.56	+	
				0	·h-	0	6.38	5.88	6.38		.50	+	
					.5	.1	6.50	7.00	95.9	.50		1	.06 EXT
1													

Include description of any personent deformation

H	ELEVATION	LOAD	9		ANGLE			EAX		21802	37		REMARKS
1	-	7-L18	nc nc	TYLLINI	LOADED	DISCOADED	INITIAL	LOADED	UNICOADED	£x7.	COMP.		
2.	SND	560	1780	15,5°	19.	1550	8.75	9.19	8.75	##.		1	
				13.5	8°	13.5	8.50	8.00	8.50		03.	+	
447-2-5-3				25°	20°	25°	10.19	9.75	152.01		the.	+	.06 .0MP.
				26°	310	270	10.38	11.00	05:01	.62		,	.12 EXT
2°	3 18	560	1780	27°	31°	270	10.50	11.00	10.50	.50		1	
				.92	20°	25.	10.31	9.75	10.25		.56	+	9 Mes 30.
				150	12°	150	8.81	8.31	18.8		. 50	+	
1				16°	21°	170	9.00	4.44	8.00	.56		1	
				0	5.	0	6.14	46.9	09.9	.50		1	.0'S EXT
				0	10	·/-	6.31	5.75	61.9		.56	+	.12 COMP
				-160	-20°	-16°	3.81	3.31	3.81		09'	+	
				-15°	-10	-140	3.94	4.44	4.00	05.		,	TX3 90.
				-240	-210	-240	2.38	2.81	2.38	.43	Notes of S	1	
	新生活的			-25°	-30	-260	2.25	1.75	61:2		05'	+	AMet 30.
2.	TILL	560	1780	-26°	-31°	-220	2.19	1.75	2.25		.56	+	RAM - 7 - FROW HORIZAL
				2/0	- 200	026-	000	000	0 2 0				

Include description of any permanent deformation

55

DATE 2/14/74

SHEET #3

REMARKS*		5 9 MP 30.		RAM S. Front	30				KAM. ANGLE 40 FROM HOR.						
		ı	+	+		1	+	+	1		+	-	-		_
CABLE	Come.		59'	50			.56	,56							
40	Ex7.	114			56	.50			.53	.56					
	UNICOADED	3.94	3.81	6.38	6.56	8.88	8.75	10.12	10.31	10.31					
3	LOADED	4.44	3.25	5.88	7.06	9.38	8.19	29.6	10.33	88.01				MAR	
	INITIAL	4.00	3.88	6.38	6.50	8.88	8.75	10.19	10.25	10.31					
	UNICOADED	-140	-110	.0	2°	140	140	.82	260	26°					
ANGLE	LOADED	-11-	-20.	-4.	5.	20°	.01	.61	30.	31.					
	DITTAL	· H ·	-15°	0	10	160	15.	240	25°	26°					
_),e	1780				0.00				2000			200		
3	FF-L35	540								630				Total	
TANAL TOR		45.11								72.4				STATE OF THE	
and the little		2.	100							N			20 1	TO SECTION AND ADDRESS OF THE PERSON ADDRESS OF THE PERSON AND ADDRESS OF THE PERSON ADDRESS OF THE PERSON ADDRESS OF THE PERSON AND ADDRESS OF THE PERSON ADDRESS OF THE PERSON ADDRESS OF THE PERSON A	

Include description of any permanent deformation

V-4 TRANSON-MOUNTED MECHANICAL STEERING STSTEM STATIC TESTING

REMARKS		- INOPERATIVE										
STEERING ARM	LOADED UNLOADED	The state of the s										
STEERI	LOADED	-62-										
	INITIAL LOADED UNLOADED	BUCK					1					
E W	LOADED											
	INITIAL	10.50										
	LOADED UNLOADED											
ANGLE	LOADED										1008	
	INITIAL	:25								2.00		
9) (1) (V)	2800	official (Desp			3 (3) (1)					N. 31	
TOAD	FT-LBS	890										
KLEVATION	11.11									The second second) with	
TILL	AMGLE O	300										

Include description of any permenent deformation

WASKIDG IN FOR ALL LOADS

*** STEERING ARM DEFLECTION

THRU-TILT STEERING SYSTEM STATIC TESTING

SINGLE INSTALLATION DATE 5-1-74

N SO HP *

	اما					-		• . 1		*	*	η	ı -	<u> </u>		5
DEFL.	UNLOA	0	0	0	0	0.	12	:12	0	112	.,9.					
RAM DEFL.	LOADED UNLOAD	O	0	.12	31	112	.25	.75	.50	:75	1.00					
CABLE	TENSION COMPRESSION	.56	.50			,50	.50		.37	.25	.31					
5	TENSION			.50	.38			.37								
	UNICOADED	2.38	2.56	2.62	2.31	6.00	5.75	3.62	9.50	9.50	9.62					
EAN	LOADED	2.00	2.12	3.25	3.19	6.50	5,83	21.01	9.25	9.25	9.19					
	INITIAL	2.56	2.62	2.75	2.31	6.00	5.38	9.75	9.62	9.50	9.50					
	UNLOADED	-26"	-26°	-23°	-240	.0.	-20	25°	240	o he	240					
ANGLE	LOADED UNILOADED	-31°	-32°	-140	-300	5°	· 6°	32°	.61	.61	13°					
	DILLIAL	- 26°	-26°	-240	-240	. 0	- 10	2.6°	240	240	240					
***	76	1920	1920	1860	1860	2090	1820	2130	2100	2620	2860					
TON	FT-LBS	388	388	388.	388	388	388	388	-388	48h	542			100	100	
THE	anger 1	-5°	12°	-5.	120	.5.	-5.	-5.	-5-		-5.					

** STEERING IMPRIKED BUT NOT INOPERABLE * DRAG ON STEERING

								*				
CALLATION	EFL.	UNLOAD		./2				62				
INS.	RAM DEFL.	LOADED	.25	.38	05'	.75	1.0	1.5.62			The second of	
S. C.	CABLE	TENSION COMPRESSION LOADED UNLOAD	.13	.13	70.	.25	90.					
	3	TENSION						13				
		LOADED UNICOADED		8.38	13			8.83			0.1.3	
	3	LOADED	8.75	29.8	18.8	8.56	8.50	29.8				
C TESTIN		INITIAL	8.88		88.8							
THEO-TILE STREETING STREET STATES		INITIAL LOADED UNLOADED		30.		1 1		170			10 P	
	ANGLE	LOADED	170	15	, 51	140	12°	110				
		INITIAL	200		200							
oprej 25	Roch	Pic Pic	1250	0 1670	2200	2490	2980	3400			4	
	362	BS	32	0	88	e.	3	0				Sin

.5.

-5°

.5.

* INOPERABLE



THRU-TILT STEERING SYSTEM STATIC TESTING

	H.	CLE
1	50 HP	SIN
	X	SINGLE
NO	4-1	UAL
LATI	V-4	M DUAL
INSTALLATION		
DUAL 1	ENCINE:	STEERING

-5' 0° 0 484 + -320 250 52 52 748 234 .25 0 .25 0 .25 0 .484 0 .484 0 .4 -320 250 52 52 259 78 234 .25 0 .25 0 .25 0 .484 0 .4 -320 250 52 52 54 .25 0 .485 0 .25 0 .25 0 .25 0 .484 0 .4 -235 262 54 .46 222 54 .262 .25 0 .25 0 .25 0 .25 0 .25 0 .484 0 .4 -235 262 54 .26 54 .26 .26 0 .25 0 .25 0 .25 0 .25 0 .25 0 .25 0 .484 0 .4 -235 257 49 49 237 51 247 0 0 0 .25 0 .25 0 .25 0 .25 0 .25 0 .25 0 .484 0 .4 -235 155 254 26 .25 176 64 .205 .06 0 .50 0 .25 0 .25 0 .25 0 .25 0 .484 0 .4 -235 155 254 0 .40 175 50 2 .25 176 .25 176 .25 0	THE	ENCINE		LOAD (FT-LBS)	LBS)	E	TIE-BAR LOAD	- Period	04	CABLES				RAM DEFLECTION	LECTION	
0° 0° 484 + .220 250 52 550 48 234 .25 0° .25 0° .25 9 40 195 .12 0° .12 0° .12 0° .12 0° .12 0° .12 0° .12 0° .12 .12 .12 0° .12	,LE	AMobile	PORT	STBD	DIR	AXIAL	TORQUE	X .	X	TORQUE	Z Z	TORQUE	LOADED	UNIOADED	LOADED	UNI.OADE
0° 484' 0 + 250 195 40 60 289 40 195 112 0	50	.0.	0	484		A 100 Sec. 10	250	25.	2.5	250	48	234	.25		.25	0
0° 184 0 -335 262 64 46 222 54 222 57 25	0	0	484	•	+	250	195	40	09	239	40	195	.12	0	.12	0
25 0 484 - 215 168 34 168 66 316 12 0 25 25 0 484 - 220 163 34 165 66 316 17 0 0 35 25 484 0 49 49 237 17 247 0 0 36 25 484 0 25 44 49 237 51 247 0 0 36 25 484 0 25 274 49 26 321 51 247 37 36 0 56 36 26 484 0 25 321 51 24 32 32 162 0 50 36 26 484 46 26 321 24 36 32 176 50 0 0 12 25 434 46 46 46 37 47 23 36 0 0 0 0 0	0		Desirate Desirate		1	-535	262	19	46	222	45	292	.25	0	.25	. <i>Ģ</i>
25° 0 484 + -220 163 34 165 66 321 0 0 75 26° 484 0 + 435 303 64 36 176 64 503 0 0 75 26° 484 0 + 435 237 49 49 237 51 247 0 0 75 26° 484 0270 205 42 52 274 49 60 321 241 0 0 50 26° 484 0270 152 34 35 27 162 175 60 0 50 0 50 26° 484 0270 155 34 35 26 176 50 0 0 50 0 0 0 50 20 0	0	0	0	484		215	168	34	34	168.	99	316	.12	0	.25	0
25° 484 0 + 435 308_ 64 36 176 64 508 0 0 50 50 25° 484 0 + 435 237 49 49 237 51 247 0 0 55° 25° 484 0 - 235 235 42 58 321 54 163 12 0 50 50 50 50 50° 55° 3484 0 - 235 155 34 64 64 308 26 176 50 0 50 50° 25° 434 0 + 355 257 49 51 247 49 237 338 0 172 25° 434 0 + 355 257 49 51 247 49 237 338 0 172 55° 544 0 + 355 257 49 51 247 49 237 33 0 172 50° 51° 51° 51° 51° 51° 51° 51° 51° 51° 51	0		- drop	484	and the same	-230	163	34	75	291	99	122	0	0	37.	0
25° 0 484 49 49 237 51 247 0 0 .28 25° 484 0 -270 205 42 53 274 412 205 .06 0 .50 35° 484 0 -250 155 34 64 74 333 36 176 0 .50 0 .50 25° 0 484 -275 145 40 40 145 50 234 .38 0 .12 25° 434 0 40 145 51 247 47 237 .38 0 .12 25° 434 0 40 145 51 247 47 237 .38 0 .12 25° 434 51 247 47 237 .38 0 .12	0		000 100 100 100		+	435	308	169	28	176	109	308	0	0	.50	.0.
75. 484 0240 205 42 53 274 42 205 06 0 .50 75. 484 0250 152 34 66 321 24 163 .12 0 0 .50 76. 0 484 - 435 203 64 (4 203 26 176 .50 0 0 .72 25. 0 484 0 + 275 145 40 40 145 60 237 .33 0 .12 25. 444 0 + 355 257 47 51 247 49 257 .53 0 .12	0	.52	plane.	184	INVESTIGATION OF	235	237	44	6#	2,37	15	247	0	0	, v	0
356 454 66 321 24 162 31 162 31 31 31 31 31 31 32	•	25.	Charles of the	1111	1	-290	305	42	53	279	12	205	90.	0	.50	c
-36° 0 484 - 435 203 64 64 64 233 20 176 50 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	•	.52.			1	-232	163	54	00	321	1/2	29/	.12	0	2	0
-35° 5 484 + -275 145 40 40 125 60 237 .38 5 .12 -25° 434 0 + 335 2:37 49 51 247 49 237 .33 0 .12	0	92	AND RESERVE	484		135	808	49	14	802	200	176	.50	0	0	0
-25° 434 0 + 335 237 49 51 247 49 237 .33 0 .12	0	.32	real country	484			.1.	40	10%	Sel	00	237	.30	0	./2	0
		-57-	434		+	335	257	43	15	247	49	237	.53	0	./2	0
												N. YORK				
				0												
																To the second

	So hp		OARD	NI.OADED			.72	13			0				0		000		在前
74	_	ECTION	STARE	TOVDED O	.33	,33 3	.75	0	2	0	0	20.	27:	:7/:	2/.				
DATE 3-4-74	IMI :	RAM DEFLECTION	PORT STARSOARD	NI.ONDED			0		iel Lei		0				.25				10 Table
DATE	DUAL INS ENGINE: STEERING CABLE		PORT	TOVDED I	0	0	0	25.	58.	.88	18:	75	32	.75	32.				
			1	TORQUE	297	351	422	303	102	40%	424	160	000	205	202	4		T	
		Sa	STAR	7	10	09	55	63	60	60	56	(N)	200	610	33				
THRU-TILT STEERING SYSTEM STATIC TESTING		CABLES	6	TORQUE	187	230	355	18Ī	23.0	345	541	324	372	4/13	472				
TILT STEERING STATIC TESTING			PORT	X	34	40	45	37	40	40	44	67	64	19	19				
THRU-TIL				2	39	10	45	37	10	40	44	33	36	29	39				
		TIE-BAR LOAD		TORQUE	187	230	353	181	230	272	341	160	209	265	302				
		TIE		AXIAL	-260	-320	- 490	-260.	022-	-330	06/1-	0227	***	152-	-425				
× .	5/1+	198		DIR	+	+	+	+	+	*+	+	1		1	1				
RECTIC	No.	TOAD (FT-1RS)		PORT STRD DIR	434	185.	775	1/9:1	183	673	775	0	0	c	c				
LOAD DIRECTION	E.			PORT	C	Ó	c	·c	C	c	6	484	183	819	27.5				
3 =		ANLONA			230	23°	23°	-270	-270	-270	-275	-270	-270	-270	-270		S. S. S. S.		
		1	643		ئن	-5.	-50	-50-	-510	.5.	.5.	. 5.	.5.	-5.	-5.				

The state of the s

THRU-TILT STEERING SYSTEM STATIC TESTING

DATE 2-26-74

SINGLE INSTALLATION

V4 | | 50 HP

760 1430 -24° -19° -24° 160 1430 -24° -19° -24° 160 1430 -26° -31° -26° 17° 1450 1430 -26° -32° -24° 1450 1430 -26° -32° -26° 1° 1430 1430 1° 5° 1° 1° 1430 1° 5° 1° 1° 1430 1° 5° 1° 1° 1° 1° 1° 1° 1° 1° 1° 1° 1° 1° 1°	TILI	TOAD	9	1000				RAM			CABLE	RAM DEFL.	DEFL.
- 460 1430 -24° -19° -24° 1.75 2.19 1.75 .44 - 460 1430 -26° -31° -26° 1.62 1.06 1.62 - 460 1430 -26° -31° -26° 1.62 1.12 1.62 - 460 1430 -26° -30° -24° 1.75 2.19 1.75 .44 - 460 1430 -26° -32° -26° 1.62 1.12 1.62 - 450 1430 -26° -32° -26° 1.62 1.12 1.62 - 450 1430 0° -4° 0° 5.00 7.75 5.00 - 1430 1° 5° 1° 5.00 5.38 5.05 .32 - 1430 0° -4° 0° 5.00 7.75 4.94 - 1430 0° -4° 0° 5.00 7.75 4.94 - 1430 1° 5° 2° 5.06 5.38 5.12 .32		FT-LBS	71	-		UNICOADED	INITIAL	LOADED	UNLOADED		COMPRESSION	LOADED UNLOAD	UNTOND
460 4450 -26 -31 -26 1.62 1.06 1.62 400. 1430 -26 -31 -26 1.62 1.12 1.62 40. 1430 -26 -30 -24 1.75 2.19 1.75 40. 1430 -26 -32 -26 1.62 1.12 1.62 40. 1430 0 -4 0 5.00 4.75 5.00 1430 1 5 1 5 1 5.00 5.38 5.02 1430 0 -4 0 0 5.00 4.75 4.94 1430 0 -4 0 0 5.00 4.75 4.94 1430 0 -4 0 0 5.00 5.38 5.02 1430 1 5 2 2 5.06 5.38 5.12 1430 1 5 5 2 5.06 5.38 5.12 1430 1 5 5 2 5.06 5.38 5.12 1430 1 5 5 2 5.06 5.38 5.12 1430 1 5 5 2 5.06 5.38 5.12 1430 1 5 5 2 5.06 5.38 5.12 1430 1 5 5 2 5.06 5.38 5.12 1430 1 5 5 2 5.06 5.38 5.12 1430 1 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	23	7160	1430	AS CULT	-160	·240	1.75	2.19	1.75	ph:		.12	
4400 1430 -26° -31° -26° 1,62 1,12 1,62 1,162 1,162 1,163 1,430 -25° -30° -24° 1,75 2,19 1,75 3,44 1,50 1,430 -26° -32° -26° 1,62 1,12 1,62 1,75 .50 1,45 1,75 1,45 1,75 1,45 1,75 1,45 1,75 1,45 1,75 1,45 1,75 1,45 1,75 1,45 1,94 1,75 1,94 1,94 1,75 1,94 1,94 1,75 1,94 1,94 1,94 1,95 1,9 1,9 1,9 1,9 1,9 1,9 1,9 1,9 1,9 1,9	20	460	1430	-26°	-31	. 5.6 .	1.62	1.06	1.62		25.	21:	
465 1430 -25° -24° 175 2.19 1.75 .44 465 1430 -24° -20° -24° 1.75 2.25 1.75 .50 465 1430 -26° -32° -26° 1.62 1.12 1.62 475 1430 10° 5° 10° 5.00 1.75 5.00 476 1430 10° 5° 10° 5.00 1.75 5.00 477 1430 10° 5° 10° 5.38 5.05 .32 478 175 10° 10° 10° 10° 10° 10° 10° 479 175 179 10° 10° 10° 10° 10° 479 175 179 10° 10° 10° 10° 479 175 179 10° 10° 479 175 179 10° 479 175 179 10° 479 175 179 10° 470 175 175 175 175 175 175 175 175 175 175	20	400.	14	RAIL TAYER	-31°	-26	1.62	1.12	1.62		.50	òс.	
** 465 1430 -24* -20* -24* 1.75 2.25 1.75 .50 ** 1450 -26* -32* -26* 1.62 1.12 1.62 ** 1450 14* 0* 4* 0* 5.00 4.75 5.00 ** 1450 1* 5* 1* 5.00 5.38 5.06 .38 ** 1450 0* -4* 0* 4.94 4.75 4.94 ** 1450 0* -4* 0* 4.94 4.75 4.94 ** 1450 0* -4* 0* 4.94 4.75 4.94 ** 1450 5* 2* 5.06 5.38 5.12 32	2°	410	1430		-30°		175	2.19	1.75	14.		.50.	
** 15.5 1450 -26° -32° -26° 1.62 1.12 1.62 1.62 1.62 1.62 1.62 1.62	3°	460	1430		-203	· 72-	1.75	2.25	1.75	.50		1.12	
** *** *** *** *** *** *** *** *** ***	130	150	1430		-35	0	1.62	1.12	0		010.	119	30.
** 1450 1430 0° 4° 0° 5.00 4.75 5.00 1450 1° 5° 1° 5.00 5.38 5.06 32 1430 0° 4° 0° 5.00 4.75 4.94 1430 0° 4° 0° 4; 0° 4; 4,75 4.94 1430 1° 5° 2° 5.00 5.38 5.12 32 1430 1° 5° 2° 5.00 5.38 5.12 32													
2° " 1450 1° 5° 1° 5.00 5.38 5.06 .38 2° " 1450 1° 5° 1° 5.06 5.23 5.05 .32 2° " 1450 0° -4° 0° 5.00 4.75 4.94 3° " 1450 1° 5° 2° 5.06 5.38 5.12 .32 3° " 1450 1° 5° 2° 5.06 5.38 5.12 .32	20	2460			o. K-		5.00	STREET, STREET	5.00		. 25	.0.8	0
1430 1° 5° 1° 5.06 5.23 5.03 .32 1430 0° -4° 0° 5.30 4.75 4.94 1430 0° -4° 0° 4.94 4.75 4.94	2		1430		5.	Some	5,00	5.38	5.06	.58		.50	:/2
. 1430 6° -4° 0° 5.30 4.75 4.94 1430 0° -4° 0° 4.74 4.75 4.94 1430 1° 5° 2° 5.06 5.38 5.12 .32		4 /	1430				5.06	5.23	50.03	.32		1.1.	ก
1430 0° -4° 0° 1494 1.75 1.94 19 5° 2° 5.06 5.38 5.12 .32	2.	"	1430	Contract of	· h-	Mary And Co.	5.30	4.75	46.4		.25	55	.19.
1° 5° 2° 5.38 5.12	30	,,			· H-	000000 /3	444	4.75	4.94		1.19	80.	0
	130		1430	10	50	10700 19674	5.06	57.38	21.5	.32		. 56	23.
	Y												

THRU-TILT STEERING SYSTEM STATIC TESTING

SINGLE INSTALLATION

													63
CFL.	UNLOAD	0	90.	./2	.12	10,							
RAM DEFL.	LOADED	29.	.75	.75	.75	7.33	1.50						
CABLE	TENSION COMPRESSION LOADED UNLOAD				42.	. 12	7						
3	TENSION	.12	12	61.									
	UNLOADED	8.17	8.19	8.17	9.50	3.62							
RAN	LOADED	12.8	8.31	8,38	8.33	8.38		٠				15/8	
	INITIAL	8.19	8.19	61.8.	8.62	3.50							
	INITIAL LOADED UNLOADED	2,50	. 52	260	42	270	30%						
ANGLE	LOADED	28°	28 3	30°	25.	22°	240						
	INITIAL	25 °	25°	. 52	28°	27°	31°						
D	Эп	- 1020	- 1240	-15 40	+13/10	+1600	+1580			name i			
QVO1	FT-LBS	230	100	500.	400	200	500						
THE	ANGLE	-5 %	° 2-	.2-	٠2-	.2-	-2.					22 10 10 10 10 10 10 10 10 10 10 10 10 10	

SYSTEM	
STEERING	TESTING
THRU-TILT S	STATIC
THE	

SINGLE INSTALLATION

DATE 3-5-74

		*									64	•
EFL.	UNTOND	.62								Section.		
RAM DEFL.	LOADED UNLOAD	1.75					10 may 2 may			245		
CABLE	TENSION COMPRESSION	1										
3	TENSION											
	UNICOADED	8.75										
RAH	LOADED											
	INITIAL	8.88							4			
	UNLOADED	28°						1				
ANGLE	LOADED	25°										
	INITIAL LOADED UNLOADED	50°										
	77	1600										
TOAD	FT-LBS	500										
H	ANGLE	-20								100 Sept. 100 Se		

* INITIAL LOAD ON THIS KAM

LOAD DIRECTION

THRU-TILT STEERING SYSTEM STATIC TESTING

DATE 2-27-74

DUAL INSTALLATION
ENGINE: X v-4 50 HP
STEERING: DUAL SINGLE
CABLE:

THE	ENGINE LOAD (FT-LBS)	LOAD	(FT-1	(38)	I	TIE-BAR LOAD			CABLES	ES			RAM DEFLECTION	LECTION	
ANGLE			-194.05					PORT	RT	STA	STARBOARD	A	PORT	STA	STARBOARD
		PORT	PORT STEP DIR	DIR	AXIAL	TORQUE	2	*	TORQUE	7	TORQUE	LOADED	LOADED UNIONDED LOADED UNIOADED	LOADED	UNI.OADED
.2.	1	0	500	+	-180	141	23	2.3	141	72	359	125	0	.25	0
- 5 -	1.	0	500	1	260	182	56	5.6	281	HH	219	.12	0	90.	0
-5.	-4.	500	0	1	-200	951	31	69	344	31	156	. 10 10	0	12/2	0
.2.	2.	500	0	+	260	1.8 2	56	HE	219	56	281	.12	0	.25	0
.2.	28.	0	500	+	-60	41.	8	00	1#	36	459.	0	0	29.	90.
.2.	.22	500	0	+	650	453	14	6	14	16	453	90.	0	29	90.
. 5 -	20,	500	0	1	c9 <i>I</i> -	117	24	76	332	24	117	0	0	.50	90.
-2.	21.	0	5,00	1	613	372	1.2	71	372	26	127	0	0	.50	0
.3	-23.	0	500	+	-160	115	. 23	23	115	77	385	.38	0	0	0
.2.	-22.	500	0	+	510	367	HL	92	.130	47	569	.38	о	0	0
-2-	-300	500	0	1	-115	78	91	34	422	16	78	.75	36.	0	0
-2°	-30°	9	500	1	595	403	18	18	403	19	26	.62	0	o	0
. 2.	-300	550	0	1	-145	98	18	28	452	18	98	50	0	.25	0
-2°	-30.	600	C	1	-165	112	19	81	488	19	112	.75	0	21.	0
-20	,12-	650	0	1	-200	134	2.1	62	516	21	134	.83.	90.	.12	0

8			61	_	_	_												
*		□ 50 HP	STEERING: ST DUAL SINGLE CABLE:		SOARD	LOADED UNIOADED LOADED UNIOADED	0	.33								T September 1	The Assessment	
7-74		7-A X	DOUAL (ECTION	STAR	LOADED	.72	1.12							0.7720			2005
DATE 2-27-74	DUAL INSTALLATION		LE : [X	RAM DEFLECTION	T	N.OADED	.12	0							Star unit			1.6.30
DATE	DUAL	ENGINE:	STEE		PORT	LOADED	1.00	0										10
						E	151	548			. ii)							
				S3	12	*	22	78		7		y						
IG SYSTEM				CABLES	I	TORQUE	549	152		1								
THRU-TILT STEERING SYSTEM STATIC TESTING					20	*	73	22										
THRU-TIL						7	61	22										
				TIE-BAR LOAD		TORQUE	151	152						,				
				TIE		AXIAL	-225	- 220					5					
z :	=	n ,	1+	88)		DIR	1	+					1-1					
ECTIO	5	7	1	(FT-L		CHIS	0	700										
LOAD DIRECTION	1	4	18	QVO.	100	PORT STRD DIR	700	0										T
YOY]	2	7	1	ENGINE LOAD (FT-LBS)	ANGLE		-31	28			4							
				TILL	145		2-	2-	•					1				

			_		_													
3	05 ET	SINGLE		STARBOARD	LOADED UNIONDED LOADED UNIONDED	0	0	0	0			21.	. 38					
1-74	LLATION	M DUAL	LECTION	STAR	LOADED	61.	12	:/2	.25	55.	50	€0.	1.12					
DATE 3-1-74	STA	STEERING: E	RAM DEFLECTION	T	NI ONDED	0	0	0	0			0	0					
DATE	DUAL IN ENGINE:	STEEL		PORT	LONDED	71.	.25	.25	.12	0	0	อ	0					
		NSIGN			1	112	37	23	399	367	439	490	009					
		IN TE	Sa	STAR	*	+00/	6	e	100	100+	1001	1001	100					
G SYSTER		וופס	CABLES		TOKOUE	1	363	377	7	1	1	•	0					
THRU-TILT STEERING SYSTEM STATIC TESTING		TIE BAR INSTALLED IN TENSIÓN 130 LBS. AXIAL		2	Y	i	16	44	0	i		1	0					
HRU-TILI STAT	land 144	130 48S.			*											<i>2</i> 7.34		
			TIE-BAR LOAD		TOKONE	77	363	23	399	207	234	250	300		100	1,000 11,00		
		Note	TIE		VXIVI	15	465	-30	510	270	335	350	420	100				
× -		^ +	BS)		DIR	+	1	1	+	+	+	+	+					
LOAD DIRECTION		1	LOAD (FT-LBS)		POKT STED DIR	400	1/00	0	0		200	240	300				6-11-	
D DIR	Lily		LOAD		NO.	0	0	400	400	160 160	200	240 240	300					
3 7		¥ 1	ENCINE	ANGLE		ိပ	.0	00	°	24.	240	240	24°				100	
			TILL	ANGLE		. 2.	-2-	.2.	-2.	-2.	.2.	-2-	-2.			17.7		

=	1
]''
	1
5	1]1
7	111

~	
SYSTEM	
=	
=	
Ž,	
~	
S	
	O
C	2
STEERING	TESTING
	_
=	52

	1
1	H
H	
S	U
	STATIC
-	-
=	-
-	-
-	S
HRU-TILT	
2	
2	
7	
-	

		So IIP	NOAL SINGLE
11-74	ALLATION	7-1	N DUAL
DATE 4-11-74	DUAL INSTALLATION	ENGINE:	STEERING CABLE

					-	-1			•				- 1	_	*	-	_
	STARBOARD	LOADED UNIOADED			0	0	0	0	0	.06	00.	0,00	21.	21.	119	61.	.25
ECTION	STAL	LOADED	.12	12	5.2.	.25	12.	(3)	W)	7) 00	.50	500	.56	29.	16		1.00
RAM DEPLECTION	PORT	LOADED UNIOADED			7	0	0	0	0				Ç)	`	.25	.25	.25
	PC	LOADED	3/:	./2	.72	./2	2/.	24.	.12	13	2/:	12	.25	573	.37	.50	.50
	STARBOARD	TORQUE	186	519	245	263	762	5/7	351	374	-403	449	172	195	558	581	219
ES	STAF	2	65	63	61	60	57	500	53	E7	50	60	59	53	53	58	56
CABLES	E	TORQUE	104	181	155	182	206	283	249	276	2.2	102	378	355	402	614	488
	PORT	8	35	37	39	40	11/2	42	24	113	211	40	114	42	24	24	hite
		2	99	63	10)	60	59	58	58	57	53	69	59	58	53	58	56
TIE-BAR LOAD		TORQUE	196	219	245	268	462	317	35+	374	403	449	472	195	558	581	6/2
111		AXIAL	260	290	325	355.	390	420	465	495	523	575	625	655	740	770	010
183	3	DIR	+														
(FT-1		PORT STBD DIR	0					ja Ling									
CAD		PORT	300	350	100	1/50	8	550	900	059	750	750	800	850	960	000/	1100
ENCTIVE LOAD (FT-1 RS)	ANGLE		150		18.8									10000		Y	
***	-		.7.				Jun.		12			1		10000000000000000000000000000000000000			

STED RAM LOOSE - ALLOWED .12 IN. DEFLECTION * ROLLED END OF

68

TO BE FOR STATE OF THE STATE OF

LOAD DIRECTION

THRU-TILT STEERING SYSTEM STATIC TESTING

DATE 4-11-74

DUAL INSTALLATION
ENCINE: X v-4 50 HP
STEERING: DUAL SINCLE
CABLE:

	_	-		 		 		 	 	
	SOARD	LOADED UNI OADED LOADED UNIOADED	61.							
LECTION	STAI	0.00.01	1.12							
RAM DEFLECTION	RT	UNIONDED	52.							
	NA NA	LOWF D	.56							
		X TORQUE	668							
ES	STAR	24	56							
CABLES		TORQUE	532			J.				
	PORT	*	44			海溢				1
		*	56							
TIE-BAR LOAD		TORQUE	668							
F		AXIAL	885							
188)		DIR.	+							
(FT-1		CHIS	0							
LOAD		PORT STED DIR.	1200			61				
ENCINE	ANGLE ANGLE		15°							
THE	ANGLE		-2.							

APPENDIX C

STEERING SYSTEM LOAD ANALYSIS

BEST_AVAILABLE COPY

ANALYSIS OF THE LOADS PRODUCED ON A THRU-TILT STEERING SYSTEM

A computer program was developed that would calculate the bending moment on the ram, the maximum stress due to this bending moment, the deflection of the end of the ram, and the force induced in the cable for any given engine steering torque. The program iterates in one degree increments through the entire range of engine travel.

The geometry of the system is shown in Figures 1 and 2. "O" is the pivot point of the engine. $"O_1"$ is the point at which the drag link connects to the steering arm. $"O_2"$ is a point on the ram at which it enters the tilt tube. This is the point that will have the maximum bending moment, M.

Following is the derivation of the equations used for the range of travel as shown in Figure 1, i.e. θ varies from 0° to 32° .

$$M_{1} = \left(x \cos \left(\arcsin \left(\frac{a \cos \theta - x - z}{d} \right) \right) \right) \left[\frac{\frac{12T}{a}}{\cos \left(\theta - \arcsin \left(\frac{a \cos \theta - x - z}{d} \right) \right)} \right]$$

$$M_{2} = \left[\frac{\frac{12T}{a}}{\cos\left(\theta - \arcsin\left(\frac{a\cos\theta - x - z}{d}\right)\right)}\right] \left(\frac{a\cos\theta - x - z}{d}\right)$$

$$\left(\cos\left(\frac{a\cos\theta - x - z}{d}\right)\right) + \sin\theta = 0$$

$$\left[d\cos\left(\arcsin\left(\frac{a\cos\theta-x-z}{d}\right)\right)+a\sin\theta-y\right]$$

In Figure 2, θ varies from -32° to 0°. In this case, $\rho = \theta + \phi$ rather than $\theta - \phi$. However, since θ is negative:

$$p = -\theta - \phi$$
 and $-p = \theta + \phi$

Since we are using the cosine of ρ , and the angle is <90°, the $-\rho$ does not change the results. Also, the moment arm of F_2 is

$$d\cos \phi - a\sin \theta - y$$
 rather than $d\cos \phi + a\sin \theta - y$

Since θ is negative and less than 90° , the sign of asin θ will automatically be negative. Therefore, the same equations can be used for a negative θ .

The maximum stress is calculated from the bending moment using an equation of the form:

$$\delta = \frac{Mc}{I}$$

The deflection of the end of the ram is calculated by superimposing the deflections due to each of the moments M_1 and M_2 .

or:
$$\delta_1 = \frac{M_1 L^2}{2EI}$$
 (L = exposed length of the ram)
$$\delta_2 = \frac{F_2 L^3}{3EI}$$
and: $\delta = \delta_1 + \delta_2$


The cable force is simply equal to F_1 .

The following assumptions apply to this program:


- 1. All motion is in the plane of rotation.
- 2. All stresses are within the elastic limit of the material.
- 3. Only small deflections occur.
- 4. There is no clearance between the ram and tilt-tube.

Due to these assumptions, the absolute values produced by the program are valid only under low loads; however, the program is valuable for determining relative values for the various parameters under higher loads as well.

The program must be run in FORTRAN on Cyphernetics. It will ask for the steering torque, which is the torque measured at the engine pivot. Attached is a program listing and a sample run for both the V-4 and 50 hp geometry.



E-80



```
000000
         1974 50 H.P. STEERING SYSTEM LUADS
000010
         THIS PROGRAM CALCULATES THE STEERING LOADS ON THE THRU-TILT
000020
         STEERING SYSTEM FOR A GIVEN STEERING TORQUE MEASURED AT THE
000030
         ENGINE PIVOT POINT.
                                -MVS
00090
          REAL I, MI, ME, LL
00106
          A=3.0
00110
          Z=5.19
00120
          X=.615
00130
          D=11.15
00140
          C=.310
00150
          F=.2275
00160
          E=30+10++6
00170
          PI=3.141592
00180
          Y≈5.5
00200
          THETA=-.5582
00220
          I = (PI + (C + 4 - F + 4))/4
00230
          CC=1/(E+I)
00300
          TYPE 10
       10 FORMAT( 'ENTER STEERING TORQUE IN FT-LBS'/)
00310
00320
       20 ACCEPT 30,T
00330
       30 FORMAT(1F)
00335
          TYPE 15
       15 FORMAT(///18X,/50 H.P. THRU-TILT STEERING LOADS/)
00336
00400
          TYPE 40,T
       40 FORMAT (//, 18H STEERING TORQUE =, F6.1, 7H FT-LBS)
00410
00420
          TYPE 45
       45 FORMAT (//
00430
                      AMGLE
                                 BENDING MOMENT MAXIMUM STRESS
004313
          (DEFLECTION CAPLE FORCE()
00440
          TYPE 50
00450
       50 FORMAT(3X, 1DEG1, 9X, 1FT-LBS1, 12X, 1PS11, 12X, 1IN1, 10X, 1LBS1)
       60 AA=((A*COS(THETA))-Z-X)/D
00500
00510
          BB=(12+T/A)/(COS(THETA-ASIN(AA)))
00520
          M1=(X+COS(ASIN(AA)))+BB
00525
          F1=COS(ASIN(AA)) *BB
00530
          M2≈BB•AA•(D•COS(ASIN(AA))+A•SIN(THETA)-Y)
00540
          BEND= (M1+M2) /12
00550
          STRESS=(BEND+12+C)/I
          LL=D+COS(ASIN(AA))+A+SIN(THETA)-Y
00560
00570
          PP=BB+AA
           DELTA1= (M1+ (LL++2)+00) /2
00580
00590
           DEL TA2= (PP+ (LL++3) +CC) /3
00595
          DECTA=DELTA1+DELTA2
          ANSLE=THETA + 180/PI
00596
00600
          PRINT 65, ANGLE, BEND, STRESS, DELTA, F1
00610
       65 FORMAT(F6.1,5%,F10.2,6%,E11.3,5%,F10.5,7%,F6.1)
00700
           IF (THETA. ST.. 5592) 50 TO 80
           THETA=THETA+.017453292
00710
00730
          50 TO 50
       30 STOP
00300
          END
00810
```

```
000000
          V-4 STEERING SYSTEM
          THIS PROGRAM CALCULATES THE STEERING LOADS ON THE THRU-TILT
000010
          STEERING SYSTEM FOR A GIVEN STEERING TORQUE MEASURED AT THE
000020
000030
          ENGINE PIVOT POINT.
                                ZVM-
00090
           REAL I,M1,M2,LL
00100
           A=9.0
00110
           Z=3.938
00120
           X=.615
00130
           D=11.44
00146
           C=.310
00150
           F=.2275
00150
           E=30+10++6
00170
           PI=3.141592
00180
           Y=5.5
00200
           THETA=-.5582
00220
           I = (PI + (C + +4 - F + +4))/4
00230
           CC=1/(E+I)
           TYPE 10
00300
       10 FORMAT( ENTER STEERING TORQUE IN FT-LBS ()
00310
90320
        20 ACCEPT 30,T
00330
        30 FORMAT(1F)
00335
           TYPE 15
00336
        15 FORMAT(///20X,/V-4 THRU-TILT STEERING LOADS/)
00400
           TYPE 40, T
90410
        40 FORMAT(//,18H STEERING TORQUE =,F6.1,7H FT-LBS)
00420
           TYPE 45
        45 FORMAT (// ANGLE
00430
                                 BENDING MOMENT MAXIMUM STRESS
00431%
           'DEFLECTION CABLE FORCE')
00440
           TYPE 50
        50 FORMAT(3%, 10851, 9%, 1FT-LBS1, 12%, 1PSI1, 12%, 1N1, 10%, 1LBS1)
00450
        60 AA=((A*CBS(THETA))-Z-X)/D
00500
00510
           BB=(12*T/A)/(COS(THETA-ASIN(AA)))
00520
           M1 = (X \bullet COS(ASIN(AA))) \bullet BB
00525
           F1=COS(ASIN(AA))+BB
           M2=BB+AA+ (D+COS (ASIN (AA)) +A+SIN (THETA) -Y)
00530
00540
           BEND= (M1+M2) /12
00550
           STRESS=(BEND+18+C) /I
00560
           LL=D*COS(ASIN(AA))+9*SIN(THETA)-Y
00370
           PP=BB+AA
00530
           DELTA1= (M1 * (LL ++2) +CC) /2
00590
           DELTA2=(PP+(LL++3)+CC)/3
00595
           DELTA=DELTA1+DELTA2
00596
           ANGLE=THETA+180/PI
00600
           PRINT 65, ANGLE, BEND, STRESS, DELTA, F1
00610
        65 FORMAT(F6.1,5%,F10.2,6%,E11.3,3%,F10.3,7%,F6.1)
00700
           IF (THETA.61..5582) 60 TO 80
00716
           THETA=THETA+. 017453292
00730
           50 TO 50
99300
        30 STOP
00310
           CHE
```

50 H.P. THRU-TILT STEEPING LOADS
STEERING TORQUE = 500.0 FT-LBS

AMBLE	BENDING MOMENT	MAXIMUM STRESS	DEFLECTION	
DE6	FT-LBS	PSI	IN ess	LBS
-32.0	57.39	0.4155+05	0.004	935.8
-31.0	53.43	0.4225+05	0.005	927.7
-30.0	59.53	0.4305+05	0.005	919.7
-29.0	60.71	0.4395+05	0.006	911.7
-28.0	61.96	0.4486+05	0.007	903.9
-27.0	63,27	0.457E+05	0.003	896.2
-26.0	64.64	0.4675+05	0.010	888.6
-25.0	65.07	0.4775+05	0.011	381.1
-24.0	67.55	0.488E+05	0.012	873.8
-23.0	69.07	0.499E+05	0.014	866.6
-22.0	70.64	0.5105+05	0.015	859.5
-21.0	72.24	0.5886+05	0.017	352.6
-20.0	73.37	0.5345+05	0.019	845.9
-19.0	75.58	0.5468+95	0.021	339.3
-18.0	77.20	0.558E+05	0.023	332.8
-17.0	78.90	0.5708+05	0.026	826.6
-16.0	80.61	0.5825+05	0.023	320.5
-15.0	33.,,,,,	0.595E+05	0.031	814.6
-14.0	34.06	0.6072+05	0.034	803.3
-13.0	35.79	0.5808+05	0.037	803.3
-12.0	87.51	0.632E+05	0.040	797.9
-11.0	89.83	0.6455+05	0.044	792.7
-10.0	90.94	0.6575+05	0.048	787.8
-9.0	92.63	0.559E+05	0.052	783.0
-9.0	94.31	0.6816+05	0.056	778.5
-7.0	95.96	0.693E+05	0.060	774.1
-6.0	97.59	0.7056+05	0.064	770.0
-5.0	99.19	0.717E+05	0.069	766.1
-4.0	100.75	0.7288+05	0.074	762.4
-3.0	102.29	0.7395+05	0.079	758.9
-2.0	103.78	0.7509+05	0.035	755.7
-1.0	105.23	0.7608+05	0.090	752.7
0.0	106.63	0.7705+05	0.096	750.0
1.0	107.93	0.780E+05	0.102	747.5
2.0	109.28	0.7895+05	0.109	745.2
3.0	110.52	0.798E+05	0.115	743.2
4.0	111.70	0.8075+05	0.188	741.5
5.0	112.32	0.3156+05	0.129	740.0
6.0	113.87	0.3236+05	0.136	738.8
7.0	114.86	0.9306+05	0.143	737.9
3.0	115.76	0.836E+05	0.150	737.3

continued

18-3

9.0	116.59	0.542E+05	0.159	737.0
10.0	117.34	0.848E+05	0.165	737.0
11.0	118.01	0.3525+05	0.173	737.3
12.0	118.58	0.357E+05	0.191	737.9
13.0	119.06	0.3602+05	0.139	738.8
14.0	119.45	0.8636+05	0.197	740.1
15.0	119.73	0.8655+05	0.205	741.7
16.0	119.91	0.3666+05	0.213	743.7
17.0	119.93	0.3675+05	155.0	745.0
13.0	119.93	0.365E+05	0.229	748.9
19.0	119.76	0.865E+05	0.237	751.9
20.0	119.47	0.8638+05	0.245	755.5
21.0	119.04	0.860E+05	0.253	759.4
22.0	119.49	0.956E+05	0.260	763.9
23.0	117.77	0.9512+05	0.267	768.8
24.0	116.98	0.345E+05	0.274	774.2
25.0	115.90	0.337E+05	0.281	780.1
26.0	114.78	0.8295+05	0.287	736.5
27.0	113.36	0.8192+05	0.193	793.6
28.0	111.31	0.8035+05	0.299	801.2
29.0	110.07	0.7952+03	0.304	809.4
30.0	103.18	0.7315+05	0.303	818.4
31.0	105.96	0.7659+05	0.311	323.0
32.0	103.56	0.7438+05	0.314	333.4

beund about

T 200 4 5 6 7 3 4 8 5

V-4 THRU-TILT STEERING LOADS

STEERING TOROUE = 500.0 FT-LBS

ANGLE	BENDING MOMENT	MAXIMUM STRESS	DEFLECTION	CABLE FORCE
DEG	FT-LBS	PSI	14	LBS
-32.0	76.57	0.5536+05	0.006	1009.7
-31.0	78.32	0.568E+05	0.007	993.1
-30.0	30.13	0.3795+05	0.003	936.8
-29.0	38.01	0.5936+65	0.069	975.5
-29.0	93.94	0.5065+05	0.010	954.6
-27.0	85.93	0.6215+05	0.012	953.9
-26.0	97.97	0.6355+05	0.013	943.3
-35.0	90.05	0.551E+05	0.015	932.9
-24.0	98.18	0.6665+05	0.017	922.8
-23.0	94.34	0.6926+05	0.019	912.8
-82.6	95.53	0.6976+05	0.021	903.1
-21.0	99.76	0.7135+65	0.023	893.6
-20.0	101.00	0.7366+05	0.035	984.3
-19.0	103.27	0.7466+05	0.023	875.3
-13.0	105.55	0.7686+05	0.031	866.5
-17.0	107.34	0.7796+05	0.634	357.9
-16.0	110.15	0.796E+05	0.037	849.6
-15.0	112.45	0.812E+05	0.041	841.4
-14.0	114.76	0.8298+05	0.044	833.6
-13.0	117.06	0.3465+05	0.048	826.0
-12.0	119.35	0.362E+05	0.032	918.5
4-11.0	121.65	0.3798+05	0.057	311.4
-10.0	123.93	0.3958+05	0.058	804.6
-9.0	126.18	0.9125+05	0.087	797.9
-3.0	128.42	0.9288+05	0.072	791.5
-7.0	130.64	0.9448+05	0.077	785.4
-6.0	132.83	0.9605+05	0.033	779.6
-5.0	135.00	0.9755+05	0.039	774.0
-4.0	137.13	0.9918+05	0.096	768.6
-3.0	139.23	0.1016+06	0.103	763.5
-2.0	141.29	0.103E+06	0.110	759.7
-1.0	143.31	0.1042+06	0.117	754.2
0.0	145.29	0.1035+06	0.125	749.9
1.0	147.22	0.1062+06	0.133	745.9
2.0	149.10	0.1035+06	0.141	742.2
3.0	150.94	0.109E+06	0.150	738.8
4.0	152.72	0.110E+06	0.159	735.6
5.0	134.44	0.1125+06	0.168	732.8
6.0	156.11	0.113E+06	0.177 0.187	730.2
7.0	157.72	0.114E+05	0.137	727.9

continued

8.0	159.27	0.1156+06	0.197	725.9
9.0	160.75	0.116E+06	0.208	724.2
10.0	162.16	0.1175+06	0.219	722.8
11.0	163.50	0.1195+06	0.230	721.8
12.0	164.77	0.1195+06	0.241	721.0
13.0	165.96	0.1205+06	0.353	720.6
14.0	167.08	0.1215+06	0.264	720.5
15.0	153.11	0.121E+06	0.276	720.7
16.0	169.06	0.1225+06	0.239	721.3
17.0	169.93	0.1236+06	0.301	722.2
13.0	170.70	0.1232+06	0.314	723.5
19.0	171.39	0.1245+06	0.326	725.1
20.0	171.97	0.1245+06	0.339	727.2
21.0	178.46	0.1256+06	0.352	729.6
22.0	172.35	0.1208+06	0.365	732.4
23.0	173.13	0.1355+06	0.378	735.7
24.0	173.30	0.1255+06	0.391	739.4
25.0	173.35	0.1855+06	0.404	743.5
26.0	173.30	0.125E+06	0.416	748.1
27.0	173.11	0.1256+06	0.489	753.2
29.0	172.30	0.1258+06	0.442	759.8
29.0	178.35	0.1252+06	0.454	764.9
30.0	171.76	0.1246+06	0.466	771.6
31.0	171.03	0.1245+06	0.473	779.9
32.	170.14	0.1236+06	0.439	786.8